

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	ile Des Experts En	Automobile	
MS	S INCOME INSURANCE LTD		Ref:	CS/INC24090310/Anh3m4	
	75 BRAS BASAH ROAD		Date:	25/11/2024	
	NCOME CENTRE SINGAPORE 189557		Code:	INC	
1.		Policy Particulars :- THIRD PARTY CLAIM			
••	Insured Veh.	SNE 8697U	Veh. Inspected	SMZ 273M	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1291282-002	Excess	\$0.00	
	Assign From	EILEEN LEE	Assign Date	17/09/2024	
2.	. Vehicle Details				
	Make & Model	KIA FORTE K3	c.c	1591	
	Engine No.	G4FGGH613262	Year of Reg.	17/06/2016	
	Chassis No.	KNAFX411MG5602776	Colour	WHITE	
	Odometer	111726 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55R16	ROADX	6	
	L/H Front Tyre	205/55R16	ROADX	6	
	R/H Rear Tyre	205/55R16	ROADX	6	
	L/H Rear Tyre	205/55R16	ROADX	6	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
THE	VEHICLE SUSTAIN		IIV.		
	EVEHICLE SUSTAIN MAGES SEE DETAIL		IN.		
DAN		S.		24/09/2024 (18:07)	
DAN	MAGES SEE DETAIL	S. General In	formation Inspection Date	,	
DAN	Accident Date	General In 19/08/2024 KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #	formation Inspection Date #01-2020, BEDOK II	,	
5a. A) T	Accident Date Survey held at HE INSPECTION W	General In 19/08/2024 KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, # 489978	formation Inspection Date #01-2020, BEDOK II arks EJUDICE" BASIS.	NDUSTRIAL PARK E, SINGAPORE	

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days