

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / ~~TP~~ RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____ km/s

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Trench had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL9907U Yr Regn: 2017, March.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV C.D. 1496.Colour: Purple A/C: Insured / Std / NI / NASp. Reading: 214626 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRU18106 X2-02049Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16.R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Prin.

Front

R/Bal. 06 mmL/Bal. 06 mmD.O.A. 18/09/24Survey held at Twin Car.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INCCOE ExpiryEstimate given during : Yes (✓)
1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Report Form / R.P. / C.P.

Days Of Repair: _____

Resurvey No. of Trip: _____

Addl Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others
