

Your Ref: 22/22/24/VP05/414127

Date: 26th September 2024

Our Ref: CS1/LPM24090342/Enh3

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia
(The Motor Claims Department)

Attn: Bayusuria Zainal

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SML 7843X
INSURED VEHICLE: JSS 6858
ACCIDENT DATE: 04/11/2022

We thank you for your instruction on 19/09/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SML 7843X from M/s Sanpoh Appraiser.
- b) Polis Diraja Malaysia of Vehicles SML 7843X and JSS 6858.
- c) Colour damaged vehicle photographs of SML 7843X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SML 7843X
Make & Model : Honda Fit 1.3gf Cvt
Chassis Number : GK31351218
Year of Registration : 2019
Engine Capacity : 1317 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.