Surveyor:

REF: CS1/LPC24090342/Enh3 (SML 7843X)

Special Instruction:

L/SUM : $12,200 / REPAIR : 6 WORKING DAYS

Third Parties:

Claimant:

Surveyor: SANPOH APPRAISER

Workshop: YEE AUTO SERVICE

ASSIGNMENT (Office)

From (Person): Bayusuria Zainal of LPC Date/Time: 19/09/2024

Estimated Cost: Bill to:

OD/TP Re-inspection **Evaluation**

To Inspect Vehicle No: SML 7843X Insured:

at Workshop m/s YEE AUTO SERVICE Tel:

of BLK 15, #01-107 SIN MING INDUSTRIAL ESTAT,E SINGAPORE 575673

Policy No: Claim No: 22/22/24/VP05/414127

Sum Insured: Excess:

Make of Veh: D.O.A. 04/11/2022

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: Confirmed with Final Fig , days (Red $ / %; Original days)

Date/Time: Submit Final Fig , days (Red $ / %; Original days)

Date/Time	Action/Instruction

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to