

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / CD RES / EVA / INV / MV  
 To in \_\_\_\_\_ vehicle No: \_\_\_\_\_  
 at \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SFWS9P Yr Regn: 2020 / July  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mercedes Benz GLE 300 1991  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 103493 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WPC2539842 F742181  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 235/55R19  
 R: 235/55R19

(Policy Condition)  
 Remark: There had commenced its repair at the time of inspection.  

N/S	O/S

  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

Front		Rear
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm
D.O.A. _____		D.O.I. <u>23/09/24</u>

  
 Survey held at One Garage  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Front O/S  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey : Yes ( )</u>
	<u>No (✓)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>0591</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Addl Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Inve (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 3 + RS. \$1 \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_