

ASS. REC. BY:

REF:

AGZ

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SNH 57042

Yr Regn:

09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

248270

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU1 1102323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

14/9/24

D.O.I.

19/9/2024

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

\$ + RS. SI

: Parking

: Others

Report Format :

Lump Sum / I.B.I. (\$) 1

TOTAL

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

Not Authorised
11 Days &
Repair After Paint
4 days

19 SEPTEMBER 2024

Auto & General Insurance (Singapore) Pte
190 Clemenceau Ave
#03-01 Singapore Shopping Centre
Singapore 239924

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SMX2032P
Accident involving vehicle no: SNH5704L/SMX2032P
DOA: 14/09/2024 at BRADDELL RD TOWARDS UPPER S'GOON RD

Dear officer in charge
Estimate cost of repair for vehicle no: SNH5704L
To supplied:

Description	Qty	Amount	
Rear bumper	<i>Bce</i> 1	532.10	<i>X</i>
Rear bumper retainer	<i>Per</i> 2	59.20	<i>X</i>
Rear bumper reflector	<i>Per</i> 2	302.20	<i>X</i>
Tailgate	<i>Per</i> 1	997.70	<i>X</i>
Tailgate lock	1	<i>12</i> 96.20	<i>X</i>
Tailgate - Honda emblem	<i>NJP</i> Ass 1	54.20	<i>X</i>
Tailgate - Vezel emblem	<i>Per</i> 1	49.80	<i>X</i>
Tailgate - H logo	<i>NJP</i> 1	24.70	<i>X</i>
Tailgate reflector	<i>Per</i> 2	553.80	<i>X</i>
Tailgate center chrome	<i>Per</i> 1	241.50	<i>X</i>
Tailgate door board	<i>Per</i> 1	331.70	<i>X</i>
End panel	<i>Per</i> 1	362.70	<i>X</i>
End panel top garnish	<i>Per</i> 1	116.50	<i>X</i>
Tailamp	<i>Per</i> 2	964.80	<i>X</i>
Boot weatherstrip	<i>Per</i> 1	131.20	<i>X</i>
Luggage compartment trim box	<i>Per</i> 1	252.30	<i>X</i>
Spare tyre tool compartment	<i>Per</i> 1	172.80	<i>X</i>
Buzzer assy, smart	<i>Per</i> 1	86.10	<i>X</i>
Rear bumper corner panel	<i>Per</i> 2	332.60	<i>X</i>
Rear wheel garnish inner trim	<i>Per</i> 2	229.80	<i>X</i>
Spare tyre panel	<i>Per</i> 1	723.00	<i>X</i>
Bumper clip	<i>Per</i>	35.00	<i>X</i>

208

Parts		6,649.90
Parts less 20%		5,319.92

1. Reverse sensor	220.00	200 JN-
2. Remove/reinstall rear windscreen glass	180.00	120 L
3. Remove/reinstall inner garnish, rear speaker hood, rear interior cushion seat, roof lining Transfer rear wiper motor to new door	160.00	60 L
4. Remove damaged parts n attachment Cut n weld damaged panels To straighten rear chassis where necessary Repair/reshape damaged areas Replace/realign all parts into same position	1,200.00	400 L
5. To spray paint	1,300.00	320 L
	8,379.92	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 18/09/2024 18:31 (SGT)
Reported by Actual Driver
Date of Accident 14/09/2024 12:45 (SGT)
Exact Location of Accident Braddell Rd, Singapore
Additional Location Information BRADDELL RD TOWARDS UPPER S'GOON RD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNH5704L

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner KH LEASING PTE LTD
Company Reg No 201611813C
Email Address KAHUPLASING@GMAIL.COM
Mobile Phone No (Phone) +65-96565553
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant SUV
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1499
Vehicle Fuel -
First Registration Date -
Chassis no -
Effective Date/Time of Ownership -

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Policy Number / Cover Note Number D23MFL0000823-01

DRIVER

100

- [illegible]

31 June

1998

100

100

Hand-drawn diagram on graph paper showing a rectangular structure. The structure is a rectangle with a smaller rectangle inside it. The outer rectangle is labeled '100' on the left and '100' on the top. The inner rectangle is labeled '50' on the left and '50' on the top. The area between the two rectangles is labeled '50' on the left and '50' on the top. The entire diagram is labeled '100' on the right.