

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/C7124090361/uvh3er**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 636 63286at Workshop m/s Amulaben

of _____

Insured: 636 55202

Policy No. _____

Claims No. SNM24D205276

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 30k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 181 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 11112780Veh No: 636 63286 Yr Regn: 18/09/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan CV350 c.c. 2488Colour: White A/C: Insured / Std / NI / NASp.Reading: 135205 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN/MC2E2670009497Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 06/05/24 D.O.I. 23/09/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction Dep 10k13-1-25 submit report vehicle hasn't send in for repair13/1/25 Submit preli report-revised fig \$2784.56 check items \$107.76

The vehicle has not send in for repair

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	444C
Vehicle Details	
Vehicle No.:	GBG6328E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2024
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	YD25000509B
Chassis No.:	JN1MC2E26Z0009497
Maximum Power Output:	-
Open Market Value:	\$25,238.00
Original Registration Date:	18 Sep 2017
First Registration Date:	18 Sep 2017
Transfer Count:	1
Actual ARF Paid:	\$1,262.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,809.00
COE Rebate Amount:	\$12,780.00
Total Rebate Amount:	\$12,780.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	


The information contained herein is correct as at 23 Sep 2024

OK



Home Used Cars Listing

All Category



Search

Save Search



2017 X

13 Vehicles

Car Make

Car Model

Price Range

Depreciation

2017

Mileage



PREMIUM AD

Nissan NV350
2.5A\$41,999
Instl. \$1,125
/mth\$12,970 /yr
1 Owner Diesel20-Dec-2017
(3yrs 2mths COE left) N.A. 2,488 cc

2 years extended warranty engine and gearbox! 24 hours towing service! Wear and tear done up! Excellent condition just like almost new, welcome for trade in with high value offer to you, bank loan and in house loan available, free accessories, call us now for viewing to believe it yourself.

ABS Bus Pte Ltd|Posted 23-Sep-2024

☐ Compare

PREMIUM AD

Nissan NV350
Microbus 2.5A\$44,800
Instl. \$1,296
/mth\$15,180 /yr
1 Owner Diesel06-Sep-2017
(2yrs 11mths COE left) 178,813 km

Trade in/loan available.

Think One Automobile & Trading|Posted 21-Sep-2024

☐ Compare

sgcarmart

Nissan NV350
2.5M\$27,888
Instl. \$878
/mth\$10,400 /yr
1 Owner Diesel31-May-2017
(2yrs 8mths COE left) N.A. 2,488 cc

Just arrived, 1 owner, Most popular van with big Boots space cargo. \$0 drive away, loan guaranteed approved. Act fast, call now for more detail

Posted 21-Sep-2024

☐ Compare

Compare

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0328/24

DATE : 16-SEP-2024

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : M/S WIS ICT PRIVATE LIMITED

ADDRESS : 29 TAISENG AVENUE

#07-01

S(534119)

TELEPHONE NO : 97724747

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 24-MAA00280-R01

VEHICLE NO : GBG6328E

MODEL CODE : MVL2RDKE26KW3GBR-D

MODEL/YEAR : NISSAN NV350 PANEL VAN AT EURO5

ENGINE NO : YD25000509B-E26AU

CHASSIS NO : JN1MC2E26Z0009497

MILEAGE : 134691 KM

DATE IN : 16/09/2024

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 06/05/2024

not authorized
merous
23/09/24
take photo before repair
H. Lys

- 9645 0084 e1mer@tanchoy.com

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for approval
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBG6328E

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RH RR FENDER, RH RR TAIL LAMP PANEL LOWER & TAIL GATE RENEW RR BUMPER	2150.00	645
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	1400.00	1050
3 ZZ/003	PERFORM RUST PROOFING LH RR FENDER AND TAIL LAMP PANEL LOWER	240.00	X
4 ZZ/004	REMOVE AND INSTALL REVERSE SENSOR	55.00	✓
5 ZZ/005	RENEW RH RR COMB LAMP	80.00	✓
	TOTAL LABOUR CHARGES	3925.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBG6328E

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1	SENSOR-REVERSE	SENSOR		11	250.00 X
2	SUNDRIES	NPN			50.00 ?
3	EMBLEM-BACK DOOR NV350	90890-3XY0A	122.40 ✓		
4	EMBLEM-REAR NISSAN	90890-JX00A	72.20 ?		
5	70KM/H STICKER	70KM/H		11	15.00 ✓
6	LABEL-PAX 10	PAX			15.00 ✓
7	CLIP RR BUMPER @ SGD\$1.50 EACH	01553-05323	15.00 ✓	11	
8	RR BUMPER	85022-3XA0A	743.00 ✓	11	
9	RH RR COMB LAMP	26550-3XA0B	275.30 ✓	11	
SUB TOTAL			1227.90	0.00	330.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			245.58	0.00	0.00
GRAND TOTAL			982.32	0.00	330.00
OVERALL TOTAL			1312.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBG6328E

TOTAL LABOUR CHARGES 3925.00
TOTAL SPARE PARTS CHARGES 1312.32

GRAND TOTAL 5237.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.