



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 ATTN: KIAN CHUAN			Ref: CS/AGI24090363/Avp3e2(N) Date: 14/04/2025 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 4755C	Veh. Inspected	SNN 9890Z
	Policy No.	P10573850R02	Coverage (\$)	0.00
	Claim No.	C10029057/KC	Excess (\$)	0.00
	Assign From	KIAN CHUAN	Assign Date	19/09/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD2120342B060063	Colour	WHITE
	Odometer	151435 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	MICHELIN	6 mm
	L/H Front Tyre	245/40 R18	MICHELIN	6 mm
	R/H Rear Tyre	245/40 R18	MICHELIN	6 mm
	L/H Rear Tyre	245/40 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/04/2024	Inspection Date	19/09/2024
	Survey held at	ONE GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	