ASS. REC. BY: Taypin - REF: C8/A14 2409 0366/TP93

<u>ASS</u>	IGNMENT.
From: Date:	Veh No: FBM 7572C Yr Regn: 2018, 03
Estimated Cost:	Type: M.Car / M.Cygle / Bus / Van / Lorry / Taxl / Prime Mover /
OD/PPYWS/TP RES/OD RES/EVA/INV/MV	Truck / Traller or
To Inspect Vehicle No:	Make: Hunda Ch 400x c.c 399
at Workshop m/s	Colour While A/G: Insured/Std/NI/NA
of	Sp.Reading — T/Radio; Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: SH2NC4790HK200022
Claims No.	Gen. Cond: God / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leakod / Burnt or
Make of Veh;	Modl: (NII) S/Rim / STD A/Rim or 1
	Tyre Size: F: 20 70817
(Policy Condition)	R: [60/60R17
Remark: The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /
repair at the time of Inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> . <u>Rear</u>
IDAC Accident Rport Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. mm
Est Repairs: days Res.: Yes or No	D.O.A. D.O.I. 20/9/24
Lum Sum: % 3 Val.: Yes or No	Survey held at /ane Scooler
CA / REV / REP. / 24 HRS	Des. of Damages Frt / Rear / OK / NTS / U/C / Rooftop- or
Date: Person Contacted: Vehicle: IN / OUT	The IIIC I Chapala from a 1 Dayle No.
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time, File Pass 107 : Prell. Report	ays Of Repair:
	Continues a Maria and the second of the seco
Dale/Time, File Return to?	Survey Fee: Transportation:
2) Add Fee;	Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Popular omital:	Tech. Invs (\$) others
Lump Sum / L.B.E. (F	: Meel:euci (it
	TOTAL

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762 Tel: 6271 4618 Email: pang_s_s_m@singnet.com.sg

ESTIMATE REPAIR

BIKE NO.: FBM7572C

DOA: 16/9/2024

MAKE/MODEL: HONDA CB400X

S/No	DESCRIPTION	AMOUNT
1	HANDLE END	\$ cut 85.00
2	HANDLE BAR	\$ 7 185.00
3	R/H MIRROR	\$ wt - 85.00
4	BRAKE LEVER	\$ bru/ 95.00
5	CRASH BAR	\$ dd/ 450.00
6	F WHEEL RIM	\$ 7 580.00
7	F BRAKE DISC	\$ 7 265.00
8	MUFFLER ASSEMBLY	\$ dd - 650.00
9	MUFFLER GUARD	\$ ad 120.00
10	UNDER BRACKET	\$ 7 285.00
11	STEERING CON (1 SET)	\$ 7 165.00
12	FORK INNER TUBE (x2)	\$? 560.00
13	FORK OIL SEAL (x2)	\$ 7 150.00
14	RADIATOR ASSEMBLY	\$ 7 480.00
15	COOLANT	\$ 7, 45.00
16	WINDSHIELD	\$ cut 285.00
17	GEAR PEDAL	\$ bt/ 185.00
18	REAR BOX	\$ wt 285.00
	LABOUR	\$ 500.00
19	LABOUR	\$ 500.00
	1 4 2016 53100	

Auto Consultants hence notify

epairer of the following: survey before/after spray painting

s, lay damaged part(s) during resurvey

, prices are subject to confirmation carry survey is on a "Without Prejudice" basis

- modification(s) is allowed rary item(s) n.ust be resurveyed and

nal approval from Insurance Company

Total: \$

5,955.00



T/20240917/7059

1 of 3

Report No. T/20240917/7059

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/09/2024 14:16			Vide Report No.:		Station Diary No.:	
Informant's	Particulars					
Name of Informant: Address: SEET LEON FRANCIS 109 GANGSA ROAD #01-147 SINGAPORE 670109				0109		
ID Type / ID No.: NRIC NO / S8327559F			Contact No.; Home/Office:	Mobile: 89211677		
Nationality: SINGAPORE CITIZEN			Email: seetleon@yahoo.com.sg			
Sex: Age: Date of Birth: Male 41 05/09/1983		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Type of Informant: Rider			
Race: Chinese			Language: English	A. C.		
Occupation: Private security officer			Driving Licence Information: Class: 2B,2A	Date of Expiry:		

General Information	of the Accident			
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/09/2024 09:40	Type of Location: Car Park
Location:			-k	—
COMPASSVALE L	ANE			*
	,			
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		affic Volume:
Type of Collision: Between Moving Ve	chicles - Head To Side			nyone conveyed by mbulance: o

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBM7572C	Motorcycle	HONDA	CB400X	White		0
SNJ3655Y	Motor car	NISSAN	SERENA 1.2 Highway Star Premium E- Power	White	Slightly Damaged	0

Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
FBM7572C	MSIG INSURANCE (SINGAPORE) PTE. LTD.	0000000300498558	09/11/2021	20/03/2025



2 of 3 Report No. T/20240917/7059

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

	Involved				
Any Pedestrian In					
No. of Pedestrians	Use of Pedestrian Crossing: NA				
Rider					
Name	SEET LEON FRANCIS		ID No.		S8327559F
Related Vehicle	FBM7572C (Motorcycle)		Contact No.		89211677
Hospital/Clinic	SHALOM CLINIC & SURGERY		Class of Driving Licence & Expiry Date		Class: 2B,2A Date of Expiry: NIL
Date Treatment	17/09/2024 Date Dis		arge	NIL	
No. of Days grante	Degree of		Slight		
Driver			r _e ffe Ye e		
Name	ANG SHU YING		ID No.		S9376980E
Related Vehicle	SNJ3655Y (Motor car)		Contact No.		NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	arge	NIL	1
No. of Days grante	d Medical Leave (MC) NIL	Degree of	Injury	NIL	

Brief Details.

i was going upwards after the level 1 ramp onto level 1B carpark and i was hit by a car on my right when the car is about to leave the carpark lot. I fell to my left and sustain injury on my left arm, right kneel cap and backache. I went to see a doctor and was given 5 days mc.



T/20240917/7059

3 of 3

Report No. T/20240917/7059

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

NP168

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 17/09/2024 14:16
Officer In Charge Of Case: TP / AEIT / LOW MENG FATT Contact No.: 97577566	Classification Of Case: