

ASS. REC. BY:

REF: TY 1

## ASSIGNMENT

Kenneth

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 842/c

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 4-5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: SUM 28536Yr Regn: 03, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda

HRV

c.c.

1496Colour: M. Green

A/C: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: 83487

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRU1810GX 201886

Gen. Cnd: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 18/9/24D.O.I. 23/9/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

NOT Authorized  
L1 Reg B  
Resurvey After Paint

## EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722  
H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500  
Email: emautosolution@singnet.com.sg

Vehicle number: SLM2853G

Vehicle Made & Model: HONDA HRV

Qty	List Items	Amount \$	
1	Tailgate	1,287.10	✓
1 set	Tailgate glass moulding	121.60	✓
1	Tailgate outer garnish	391.40	X
1	Tailgate emblem logo	48.80	X
1	Tailgate emblem "HRV"	68.80	✓
1	Tailgate emblem "i-VTEC"	68.80	✓
2	Tailgate lamps - L/R @ 410.20	820.40	X
1	Tailgate inner lock	281.30	?
1	Tailgate inner trim board	481.60	X
1	Tailgate inner pull pocket	86.90	X
1	Tailgate w/strip	210.20	?
2	Tailgate dampers - L/R @ 186.10	372.20	X
2	Tailgate stoppers @ 12.60	25.20	X
2	Taillamps - L/R @ 488.10	976.20	X
1	Rear bumper	791.60	✓
2	Rear bumper reflectors - L/R @ 89.90	179.80	X
2	Rear bumper sides - L/R @ 241.20	482.40	X
2	Rear bumper side retainers - L/R @ 48.60	97.20	X
1	Rear end panel	659.10	?
1	Rear end panel garnish	211.60	?
1	Rear exhaust silencer	576.50	X
1	Rear exhaust insulator	120.30	X
2	Rear exhaust mountings @ 28.20	56.40	X
1	Rear floor board	370.60	X
1	Rear floor sponge tray	321.60	?
1	Rear floor panel	871.90	X
1	Rear floor panel undercover	286.90	X
2	Rear fender protectors - L/R @ 341.60	683.20	X
1	Rear smart keyless antenna	191.20	?
1	Rear smart keyless buzze	199.60	?
Sub-total		11,340.40	
Less 20%		2,268.08	
Total List		9,072.32	

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and  
is subject to final approval from Insurance Company

Page 1 of 2

Acknowledged by Repairer

Signature:

Date:



Vehicle number: SLM2853G

Vehicle Made & Model: HONDA HRV

**Special Nett Items**

1 set	Tailgate glass sealant	80.00	405N
1 set	Tailgate outer garnish clip	80.00	X
1 set	Rear bumper clip	50.00	✓
1 set	Rear no. plate	60.00	X
1	Rear reverse camera	450.00	X
1 set	Rear reverse sensor - 4 Pcs	480.00	?
<b>Total Special Nett</b>		<u>1,200.00</u>	

**Labour charges**

To check rear electrical wiring	50.00	201
To remove, refix tailgate glass	180.00	1201
Transfer & reinstall tailgate components to new tailgate	150.00	601
To remove, refix rear interior trims to assist repair	120.00	?
To remove, refix rear reverse sensor / camera	80.00	602
To remove, refix rear exhaust	80.00	X
To respray undercoating	120.00	?
To respray painting and etc	1,200.00	6001
Panel beating, cut, weld remove & replacing above parts	1,400.00	?
<b>Total Labour</b>	<u>3,380.00</u>	

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,652.32**



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of First Submission	19/09/2024 16:25 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	18/09/2024 17:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BEDOK RESERVOIR ROAD TURNING INTO BEDOR RESERVOIR VIEW
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM2853G

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG MUN SAM
NRIC No	S1598676Z
Email Address	SAMNCHOO@SINGNET.COM.SG
Mobile Phone No	(Phone) +65-96683713
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	HRV 1.5 DX CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496
Vehicle Fuel	Petrol
First Registration Date	27/03/2017
Chassis no	JHMRU1810GX201886
Effective Date/Time of Ownership	27/03/2017 10:03 (SGT)

#### INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Policy Number / Cover Note Number	MP321860

#### DRIVER



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)



Sketch Plan



(A) SLM 2853 G

(B) SLR 5567 L

Bedok Reservoir Road Turning to Bedok Reservoir View