



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO24090384/Anp3m4
(N)

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Date: 06/01/2025

ATTN: JIA YI

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 4188R	Veh. Inspected	SLQ 7241T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2403060/JYC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/09/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV 1.5 LX CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1830GX202511	Colour	BLUE
Odometer	130053 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	6 mm
L/H Front Tyre	215/60R16	DUNLOP	6 mm
R/H Rear Tyre	215/60R16	DUNLOP	6 mm
L/H Rear Tyre	215/60R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/09/2024	Inspection Date	23/09/2024
Survey held at	1 CORPORATION DR #02-17, REVV TAMAN JURONG S619775		
Repairer	ELITE AUTOMOTIVE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
--	------------------------