Steve

REF:

## CS/SMR24090387/Enp3

ASSIGNMENT

From: Date:	Veh No: SLE7342Z Yr Regn: 29 Jul 2016
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: VOLKSWAGEN JETTA c.c 1390
at Workshop m/s	Colour White A/C: Insured / Std / NI / NA
of	Sp.Reading 133498 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WVWZZZ16ZGM017896
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 225/40ZR18
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 19/09/24 D.O.I. 25/09/24
Lum Sum: % 3 Val.: Yes or No	Survey held at Teamwork Garage
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV - \$27k	
Estimate give later	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
1) : Final Report  Date/Time, File Return to?	Transportation:
Add Fe	The state of the s
2)	: Interview (\$ ) Photos
Mary A. Paraccair s	: Tech. Invs (\$ ) Others
Report Formal :	: Westend (\$
Lump Sum / I.B.J: (%)	TOTAL
	177174