

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 23.09.2024MODEL: Toyota PriusVEHICLE NO.: SH 6683YINSURANCE: SMB8029B
SMRT BUSMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Wing Mirror LH / <i>BR</i>	1		\$ 1,390.10
	Wing Mirror Outer Cover LH / <i>MIS</i>	1		\$ 141.90
	Front Fender (Hybrid) LH / <i>NPC</i>	1		\$ 86.50
	SUB TOTAL			\$ 1,618.50
	LESS 25%			\$ 404.63
	DISCOUNTED TOTAL			\$ 1,213.88
	Front Door (ComfortDelGro) LH / <i>NPC</i>	1		\$ 75.00
	Front Door Adv.Sticker LH / <i>NPC</i>	1		\$ 100.00
	Front Fender Adv.Sticker LH / <i>NPC</i>	1		\$ 100.00
	NETT TOTAL			\$ 275.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 700.00
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,588.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (LKK)
23/9/24, 3:30pm

LK
L/S

by AL ly
3 = 2 days

2428.88

L/S - 1943.10
= 1950

940

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Toyota Prius