

Our Job Ref No : 305604658
Date : 28.09.2024

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : STEVE CHEN

Vehicle Reg No. : SH 6683Y

Date of Accident : 23.09.2024

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MS FIRST CAPITAL --- **SMRT BUS**
SMB8029B
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges (include advertisement stickers etc,if any) _____
- Total for Part-By-Part Repair Cost** _____
- (c.) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% \$1,950.00
- Final Lumpsum Repair cost** \$1,950.00

3 -Noted same 03 repair days on 30/09/24

3. Estimated normal period for repairs: 2 + 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Signature : _____

Name : LIM T S

Name : STEVE

Tel : 62148398

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	---	--		
4. LTA Search Fee / GEARS	\$27.25 / \$2.18	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

