| ESt. Repairs. | days | | | | | |
|---------------|-----------------------------------------------------------------|-------------------|----------------|--------------------------------|--|--|
| Lum Sum: | % | 3 Val.: Yes or No | Survey held at | One Colour | | |
| CA / REV / | REP. / 24 HRS | Vehicle: IN / OUT | | Frt / Rear / O/S / N/S / U/C / | | |
| | A C / / - / I - for estion | | | | | |
| Date / Time | Action / Instruction Workshop is sub-contractor - No GIA report | | | | | |
| | Repair rang | ge \$2k - \$3k | | | | |
| | 3 days | | | | | |
| | | | | | | |
| | | | | | | |

| Date/Time, File Pass to? | : Preli. Report | Days | of Repair: | |
|----------------------------|-----------------|----------|-----------------|-----------------|
| 1) | : Final Report | Resi | Survey Fee: | |
| Date/Time, File Return to? | leccond. | | | Transportation: |
| 2) | | Add Fee: | : Site Insp (\$ |)s+Rssi |
| | | | : Interview (\$ |) Photos |
| Reporter: | | | :Tech. Invs (\$ |) Others |
| Lumin Saum I F R 1: CS | | \ | : Weel:end (\$ | 1 |