

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24090392/Rnp3e2	
	(BUDGET DIRECT INSURANCE)		Date:	11/10/2024	
	190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924		Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGR 2409P	Veh. Inspected	SBA 5252C	
	Policy No.	P10856082R01	Coverage	0	
	Claim No.	C10031815/KR	Excess	\$0.00	
	Assign From	KAVIDHA RAJAN	Assign Date	23/09/2024	
2.	2. Vehicle Details				
	Make & Model	CHEVROLET ORLANDO 1.4AT	C.C	1362	
	Engine No.	B14NET170070294	Year of Reg.	28/06/2017	
	Chassis No.	KL1YA7589HK613618	Colour	BROWN	
	Odometer	1362 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60 R16	FALKEN	6	
	L/H Front Tyre	215/60 R16	FALKEN	6	
	R/H Rear Tyre	215/60 R16	FALKEN	6	
	L/H Rear Tyre	215/60 R16	FALKEN	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	20/09/2024	Inspection Date	25/09/2024	
	Survey held at	5, SOON LEE STREET, #01-54, PION	EER POINT - REPA	IRER: COMPLETE VMS PTE LTD	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days