

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN		Ref:	CS/INC24090411/Avh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES		Date:	23/01/2025	
	ATTN: ENG HUEY	HUEY		Code:	INC
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLZ 7100U	Veh. Inspected	t	SDA 1129D
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1295977-003	Excess (\$)		0.00
	Assign From	JESS TOH	Assign Date		24/09/2024
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC	c.c		1597
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	MRHFC5650GT000798	Colour		BLUE
	Odometer	74243 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/55R16	WEST LAKE		6 mm
	L/H Front Tyre	215/55R16	WEST LAKE		6 mm
	R/H Rear Tyre	215/55R16	WEST LAKE		6 mm
	L/H Rear Tyre	215/55R16	WEST LAKE		6 mm
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/09/2024	Inspect Date /	Time	24/09/2024 (04:34 PM)
	Survey held at JL PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		10 Work	ing Days