



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24090432/Knp3e2
50 RAFFLES PLACE #03-03	Date:	06/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 6513X	Veh. Inspected	SMM 5281A
Policy No.	-	Coverage	0
Claim No.	CMTD2403081/JYC	Excess	\$0.00
Assign From	JIA YI	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	HONDA FIT (A)	C.C	1496
Engine No.	LEB1446821	Year of Reg.	02/07/2019
Chassis No.	GP51338702	Colour	METALLIC BLACK
Odometer	676674 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55R15	BLACKHAWK	8
L/H Front Tyre	195/55R15	BLACKHAWK	8
R/H Rear Tyre	195/55R15	BLACKHAWK	8
L/H Rear Tyre	195/55R15	BLACKHAWK	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/09/2024	Inspection Date	29/11/2024
Survey held at	5034 ANG MO KIO INDUSTRIAL PARK 2 #01-341 SINGAPORE 569537 - REPAIRER: JD MOTORSPORTS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days