## CS/FCI24090433/Aqp3

ASSIGNMENT	
Figit≢ Date:	Veh No: SLU69744 YT Regn: 2017, Dec
Estin = Educit	Type: M.Can / M.Cycle / Bus / Van / Lorry / T.axi / Prime Mover /
OD / TRISITP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To in thicle No:	
at WO Filipm/s	107112 (1) 2
cí	- Wo. Madred / SIU / NI / NA
Insur@d:	Sp.Reading 132794 T/Radio: Insured / Std / NT / N.A Eng/No:
Policy Na	
Claims S M	C/No: ZYX102081926:
Sum Ensur	Gen. Cond: 660 / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
Make of Valor	Modi: Nil S/Rim / STD A/Rim or
12 - Doug triple 4, 200 00 3 - 2, 0, 00	Tyre Size: F: 275/50R18
(Policy Condition)	R: 225/50R/8
Remark: Theyeh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / L IZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF KAPSEA.
Bal. or Malatvalue:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
	L/Bal. 06 mm L/Bal. 15 mm
Est. Repair: 4 days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	D.O.A. D.O.I. 25/09/24.
	Survey held at Hutomobile. While
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The state of the s
79 Ist Cap. COE Expiry:	
LS \$2100, 4 days (Red \$9685.15,	
mv: 514	Estimate given during: Yes ()
PV: [9.8K	1st Survey No (1)
Nett: 31-2K	
	9306.
Daterine, File Pass to?	
OOMO T	Days Of Repair: 4
Datamina, File Return to?	Resurvey No. of Trip: 1 Survey Fee:
2) Add Fe	Transportation:  Site Insp (\$ ) 8+R8.81
E. TD	: Interview (% ) Photos
Fraport Formuse: TP	: Tech. Inver(3" ) Others