SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 20/06/2024 18:52 (SGT) Reported by **Actual Driver** Date of Accident 19/06/2024 18:50 (SGT) Exact Location of Accident 80 Airport Blvd., Singapore Changi Airport, Singapore 819642 Additional Location Information CHANGI AIRPORT TERMINAL 1, CARPARK LVL B2M, LOT 19 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

2995

Vehicle Registration Number SDA7818J

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LOW BOON SOON NRIC No SXXXX524E Email Address Ericlowbs@gmail.com Mobile Phone No (Phone) +65-96633730 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Audi Model A8I Variant D5 3.0 TFSI QU Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Private car Transmission Auto

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number 1900080269-04

DRIVER

CC

Name of Driver TAN GEOK LENG NRIC No SXXXX682I Date Of Birth 11/05/1973 Occupation Indoor

Driving Pass Date 27/11/1992 Driving experience 31 YEARS AND 7 MONTHS Gender Mobile Number (Phone) +65-96829728 Alt. Phone Number Email Address TANGEOKLENG.TGL@GMAIL.COM Address 13 BEDOK RESERVOIR VIEW Address complement #18-03 Postcode 478932 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Relative Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Fire, explosion or lightning Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? No Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name REPORT NO. P/20240619/0055 Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO THE ATTACHMENT. ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes



SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (ii) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time 06 W

Witnessed by Reporting Centre tony Foony Personnel

Sketch Plan

sketch plan available No

1. Mr Eric Low drove to Bedok Reservoir to pick up Tan GL around 1810hrs. 2. Tan GL drove to Changi Airport T1, parked at T1 carpark Ivl B2M approximately 1830hrs. Eric checked in for flight. 3. Notified via Changi airport PA system around 1850hrs, Eric received call around 1900hrs informing that SDA7818J caught fire. 4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage. 10. Vehicle towed from T1 carpark around 2140hrs.
2. Tan GL drove to Changi Airport T1. parked at T1 carpark Ivl B2M approximately 1830hrs. Eric checked in for flight. 3. Notified via Changi airport PA system around 1850hrs. Eric received call around 1900hrs informing that SDA7818J caught fire. 4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9. SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
S. Notified via Changi airport PA system around 1850hrs, Eric received call around 1900hrs informing that SDA7818J caught fire. 4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9. SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
S. Notified via Changi airport PA system around 1850hrs, Eric received call around 1900hrs informing that SDA7818J caught fire. 4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9. SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
3. Notified via Changi airport PA system around 1850hrs. Eric received call around 1900hrs informing that SDA7818J caught fire. 4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow.
4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
4. Tan GL arrived at carpark B2M around 1902hrs, police officers, airport firefighters and CAG executives were on site, around the car, equipped with fire fighting equipments. 5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 scalled Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 scalled Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
5. Surrendered key to fire fighter whom later asked if the window can be wind down, pressed unlock button on key fob to partially wound down the window, smoke bellowed out. 6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
6. No naked fire detected when fire fighters opened opened the door, no water or chemicals used. 7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
No naked fire detected when fire fighters opened opened the door, no water or chemicals used. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 scalled Audi 24hrs roadside assistance for tow. SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
7. Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
Statements taken by police officers and SCDF officers. Report Number: P/20240619/0055 8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
8. called Audi 24hrs roadside assistance for tow. 9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
9.SCDF IO arrived on scene around 2100hrs, investigated vehicle, assessed damage.
10. Vehicle towed from T1 carpark around 2140hrs.
10. Vehicle towed from T1 carpark around 2140hrs.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel Tony Foeny































































































































































GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours: Monday to Friday, 09:00 – 17:00 UEN: \$66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: _Vehicle Registration No: SDA 7818 J Original Report No : SP14246K0006 Name(as shownin NRIC) : LOW BOON SOON __NRIC/FIN/PassportNo : SXXXX524E (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate . 13 BEDOK RESERVOIR VIEW, #18-03 Address _Singapore(478932) _Mobile No. :_96633730 Contact (Tel) . Ericlowbs@gmail.com **Email Address** _Time of Accident: 18:50 . 19/06/2024 Date of Accident : CHANGI AIRPORT TERMINAL 1, CARPARK LVL B2M, LOT 19 Place of Accident Insurance Company: AIG Asia Pacific Insurance Pte. Ltd. (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: TO AMEND OWNER'S EMAIL ADDRESS Policyholder / Driver's Signature Reporting Centre Personnel's Signature TONY FOORY Date: Name:

NRIC/FIN No.: Date:

GIARMC redendumlana, V.