

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	•		
MS	LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Ref:	CS/LIP24090439/Unh3e2	
			Date:	17/10/2024	
			Code:	LIP	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMX 3873Y	Veh. Inspected	SKD 2213M	
	Policy No.	-	Coverage	0	
	Claim No.	IVS24/1799	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	24/09/2024	
2. Vehicle Details					
	Make & Model	VOLKSWAGEN NEW GOLF 1.4 (A)	C.C	1390	
	Engine No.	CAX955931	Year of Reg.	10/11/2011	
	Chassis No.	WVWZZZ1KZCW108795	Colour	WHITE	
	Odometer	173309 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55R16	PIRELLI	6	
	L/H Front Tyre	205/55R16	PIRELLI	6	
	R/H Rear Tyre	205/55R16	PIRELLI	6	
	L/H Rear Tyre	205/55R16	PIRELLI	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	20/09/2024	Inspection Date	25/09/2024	
	Survey held at AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				