



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24090457/Knp3m4
50 RAFFLES PLACE #03-03	Date:	15/10/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 6993S	Veh. Inspected	SKX 8361Z
Policy No.	-	Coverage	0
Claim No.	CMTD2403028/SYH	Excess	\$0.00
Assign From	SHIANG YI	Assign Date	25/09/2024

2. Vehicle Details

Make & Model	BMW 116D (A)	C.C	1496
Engine No.	33759419B37D15A	Year of Reg.	29/12/2015
Chassis No.	WBA1V72050V250362	Colour	METALLIC BLUE
Odometer	171684 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40R18	PIRELLI	7
L/H Front Tyre	225/40R18	PIRELLI	7
R/H Rear Tyre	225/40R18	PIRELLI	7
L/H Rear Tyre	225/40R18	PIRELLI	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/09/2024	Inspection Date	02/10/2024
Survey held at	LIAN HER MOTORWORKS - 5034 ANG MO KIO INDUSTRIAL PARK 2, #01-337, SINGAPORE 569537		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days