



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.  
60 WOODLANDS INDUSTRIAL PARK E4  
SINGAPORE 757705

INV No. : SAC2401002

INV Date : 15-10-2024

Reference CS/SMR24090458/Knp3e2

Code SMR

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLP 8631A  
Insured Veh. SHB 5347L  
Claim No. TAX/09/24/2058  
Policy No.  
Accident Date 19/09/2024  
Inspection Date 02/10/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

**LKK Auto Consultants Pte Ltd**

***KHM***

---



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Ref: CS/SMR24090458/Knp3e2 Date: 11/10/2024 Code: SMR
---	---

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 5347L	Veh. Inspected	SLP 8631A
Policy No.	-	Coverage	0
Claim No.	TAX/09/24/2058	Excess	\$0.00
Assign From	HUA YEN	Assign Date	25/09/2024

### 2. Vehicle Details

Make & Model	SUBARU FORESTER XT (A)	C.C	1998
Engine No.	FA20B978397	Year of Reg.	21/06/2017
Chassis No.	JF1SJGK85HG088207	Colour	METALLIC PEARL WHITE
Odometer	219227 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R18	YOKOHAMA	8
L/H Front Tyre	225/55R18	YOKOHAMA	8
R/H Rear Tyre	225/55R18	YOKOHAMA	3
L/H Rear Tyre	225/55R18	YOKOHAMA	3

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/09/2024	Inspection Date	02/10/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) - 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLP 8631A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE LOGO	NECESSARY	\$98.00	\$98.00
1	TAILGATE EMBLEM SUBARU	NECESSARY	\$95.00	\$95.00
1	TAILGATE EMBLEM FORESTER XT	NECESSARY	\$85.00	\$85.00
1	REAR BUMPER	BENT	\$769.00	\$769.00
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	\$38.00	\$0.00
1	REAR BUMPER TOW COVER	SERVICEABLE	\$28.00	\$0.00
1	REAR BUMPER REINFORCEMENT	BENT	\$420.00	\$420.00
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	\$888.00	\$0.00
2	REAR EXHAUST MUFFLER RUBBER @\$30.00	SERVICEABLE	\$60.00	\$0.00
1	REAR END PANEL	BENT	\$458.00	\$458.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	\$68.00	\$0.00
	<b>LESS 10.00 / 20.00% DISCOUNT</b>		(\$300.70)	(\$385.00)
			\$2,706.30	\$1,540.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	REAR BUMPER CLIP (SN)	NECESSARY	\$60.00	\$60.00
1	REAR BUMPER LOWER SPOILER (SN)	NO SUCH PARTS	\$1,660.00	\$0.00
1	REAR BUMPER LOWER SPOILER CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
			\$1,840.00	\$60.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND LIGHT SYSTEM		\$60.00	\$15.00
	APPLY BODY SEALANT ON BODY PARTS		\$50.00	\$30.00
	TO RUSTPROOF ACCIDENT DAMAGE AREA		\$50.00	\$30.00
	TO REMOVE/REFIX EXHAUST SYSTEM	NOT NECESSARY	\$150.00	\$0.00
	TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER		\$100.00	\$50.00
	TO REMOVE NECESSARY PARTS, TO REPAIR INNER PANEL, CUT OUT ACCIDENT DAMAGE PANEL, REWELD PANEL, REPLACE DAMAGE PARTS AND ALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR EXHAUST MUFFLER		\$700.00	\$600.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
TO PUTTY/RESPRAY TAILGATE, REAR BUMPER, END PANEL		\$800.00	\$640.00
		\$1,910.00	\$1,365.00
<b>GRAND TOTAL</b>		<b>\$6,456.30</b>	<b>\$2,965.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$2,350.00</b>
<b>Report Ref No: CS/SMR24090458/Knp3e2</b>			

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of First Submission ..... 19/09/2024 15:50 (SGT)  
Reported by ..... Actual Driver  
Date of Accident ..... 19/09/2024 09:10 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... BRADDELL ROAD TO FARRER ROAD  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLP8631A

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... CHEW GEK ENG  
NRIC No ..... SXXXX549Z  
Email Address .....  
Mobile Phone No .....  
Alternative Phone No .....

### VEHICLE PARTICULARS

Manufacturer ..... Subaru  
Model ..... Forester  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1998  
Vehicle Fuel ..... -  
First Registration Date ..... -  
Chassis no ..... -  
Effective Date/Time of Ownership ..... -

### INSURANCE COMPANY

Name of Insurance Company ..... Great Eastern General Insurance Limited  
Policy Number / Cover Note Number ..... V5015559

### DRIVER

Name of Driver .....	TAY CHONG SENG
NRIC No .....	SXXXX595D
Date Of Birth .....	27/10/1964
Occupation .....	Outdoor
Driving Pass Date .....	
Driving License Pass Class .....	3
Driving License Validity .....	Valid
Driving experience .....	42 YEARS AND 6 MONTHS
Gender .....	Male
Mobile Number .....	
Alt. Phone Number .....	
Email Address .....	
Address .....	
Address complement .....	-
Postcode .....	-
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Spouse
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Head to Rear
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SHB5347L
Vehicle Manufacturer .....	-

Vehicle Model ..... -  
Vehicle Variant ..... -  
Vehicle Colour ..... -  
Vehicle Category ..... Taxi  
Name of Driver ..... -  
Contact Number ..... -  
Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



**Describe Circumstances of the Accident**

*Refs attached*

**Declaration**

I/We declare the foregoing particulars are true in every respect.

*[Handwritten signature]*

 *[Handwritten signature]*

\_\_\_\_\_  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

I would like to report a car accident at  
 Lornie Highway <sup>(Heading to PIE)</sup> this morning between 9.10 to 9.20am.  
~~There~~ I was on the right most lane of a 4 lane  
 Road. Direction (From Braddell Road to Farrer Road.)  
 There was a small jam. I was at a Stop position  
 after the car in front ~~was~~ could not move forward.  
 Suddenly a Stride Taxi (Licence: SHB 5347L)  
 Driven by Mr. Chan Ah Wat. (S1309029G). He  
 could not brake on time & crashed into ~~the~~ the  
 back of my Subaru Forester. The front  
 bonnet & bumper of the taxi was damaged.  
 My Rear end bumper was ~~so~~ scratched. damaged  
 & My lower bumper was broken. We  
 exchange particulars & phone contact & left  
 the scene. I have a video dash cam footage of  
 the accident.

My Mobile: 96314818

Mr. Tay Chong Seng

Taxi Driver:

Mr Chan Ah Wat

Mob: 97232926



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 1 of 4)

### PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 3 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 4 of 4)

## PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 8631A

