

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS MS FIRST CAPITAL IN		INSURANCE LTD	Ref:	CS/FCI24090461/Avp3m4	
	16 RAFFLES QUAY #42-01 HONG LEONG BUILDING		Date:	12/11/2024	
	#42-01 HONG LEO SINGAPORE 04858		Code:	FCI2	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7537L	Veh. Inspected	SND 680A	
	Policy No.	D-24101860MFCT	Coverage	0	
	Claim No.	D24008369MFCT	Excess	\$0.00	
	Assign From	JOANNE	Assign Date	25/09/2024	
2.	2. Vehicle Details				
	Make & Model	NISSAN SERENA	c.c	1198	
	Engine No.	HR12138335K	Year of Reg.	06/04/2020	
	Chassis No.	JN1EBAC27Z0000474	Colour	BLACK	
	Odometer	92940 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/60R16	YOKOHAMA	6	
	Torri Torre Tyre	100,00111			
	L/H Front Tyre	195/60R16	YOKOHAMA	6	
			YOKOHAMA YOKOHAMA	6 6	
	L/H Front Tyre	195/60R16			
4.	L/H Front Tyre R/H Rear Tyre	195/60R16 195/60R16	YOKOHAMA YOKOHAMA	6	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195/60R16 195/60R16 195/60R16	YOKOHAMA YOKOHAMA of Damages	6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195/60R16 195/60R16 195/60R16 Description of ED DAMAGES AT THE FRONT PORTION	YOKOHAMA YOKOHAMA of Damages	6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195/60R16 195/60R16 195/60R16 Description of ED DAMAGES AT THE FRONT PORTION	YOKOHAMA YOKOHAMA of Damages ON.	6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195/60R16 195/60R16 195/60R16 Description of ED DAMAGES AT THE FRONT PORTIONS.	YOKOHAMA YOKOHAMA of Damages ON.	6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre EVEHICLE SUSTAIN MAGES SEE DETAIL	195/60R16 195/60R16 195/60R16 Description of ED DAMAGES AT THE FRONT PORTIONS. General Info	YOKOHAMA YOKOHAMA of Damages ON. formation Inspection Date	6 6 30/09/2024	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL Accident Date	195/60R16 195/60R16 195/60R16 Description of ED DAMAGES AT THE FRONT PORTIONS. General Info 21/09/2024 XIN YUN AUTO PTE LTD – BLK 8 KAK	YOKOHAMA YOKOHAMA of Damages ON. formation Inspection Date KI BUKIT AVENUE 4	6 6 30/09/2024	

Estimate Days of Repair