



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24090470/Aqh3m4(N)

Date: 28/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7991P	Veh. Inspected	SLS 2677S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1295918-002	Excess (\$)	0.00
Assign From	JESS TOH	Assign Date	25/09/2024

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MJ5743864	Colour	RED
Odometer	121945 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45R17	KUMHO	6 mm
L/H Front Tyre	215/45R17	KUMHO	6 mm
R/H Rear Tyre	215/45R17	KUMHO	6 mm
L/H Rear Tyre	215/45R17	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/09/2024	Inspect Date / Time	26/09/2024 (01:59 PM)
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**