



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: AZHARI

Ref: CS/INC24090477/Avh3m4(N)

Date: 22/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 9761Z	Veh. Inspected	SLQ 6068J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1296902-002	Excess (\$)	0.00
Assign From	JESS TOH	Assign Date	26/09/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102007011	Colour	WHITE
Odometer	70837 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R18	MICHELIN	6 mm
L/H Front Tyre	225/50R18	MICHELIN	6 mm
R/H Rear Tyre	225/50R18	MICHELIN	6 mm
L/H Rear Tyre	225/50R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/09/2024	Inspect Date / Time	26/09/2024 (04:12 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**