

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURA	NCE PTE LTD	-	Ref:	CS/LIP24090484/Avh3m4(N)	
	ONE RAFFLES QU #25-01 NORTH TO	JAY WERSINGAPORE 048583		Date:	07/02/2025	
	ATTN: ANDY SEAF	1		Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XD 2862K	Veh. Inspected		GBB 3380Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	IVS24/1806	Excess (\$)		0.00	
	Assign From	ANDY SEAH	Assign Date		26/09/2024	
2.	2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT PARTNER L2 1.6 AT	c.c		1560	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	VF37FBHYMGJ910812	Colour		BLACK	
	Odometer	78495 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	NEXEN		6 mm	
	L/H Front Tyre	195/65R15	NEXEN		6 mm	
	R/H Rear Tyre	195/65R15	NEXEN		6 mm	
	L/H Rear Tyre	195/65R15	NEXEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	20/09/2024	Inspection Date	е	26/09/2024	
	Survey held at	JEC AUTO SERVICE PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-77 AUTOBAY				
		SINGAPORE 417883				
5a.						
	A)REGISTRATION DATE: 23 JUN 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 11 Working Days					
	-					