

REF:

CS/SMR24090491 / Avp3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W/O _____

of _____

Insured: **SHB 1183T**

Policy No: _____

Claim No: **TAX/09/24/2084**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMW86201** Yr Regn: **2020, Dec**Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Yaris Cross** C.D. **1490**Colour: **Red** A/C: Insured / Std / NI / NASp. Reading: **167532** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JTDKBA B3X0L002689**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: **215/60R16**R: **215/60R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal. **86** mm R/Bal. **86** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. **25/9/24** D.O.I. **27/09/24**

Survey held at

BifrostDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 8MRT**3/12/24 LS \$5600 confirmed by email (Red 11,619.50, 67%)**

COE Expiry:

Estimate given during: Yes ☒ No ☐
1st Survey

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

2)

☐

Final Report

Days Of Repair: **6**

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Report Format:

E. Report Form / I. P. P. / C.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	895N

Vehicle Details

Vehicle No.:	SMW8620H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	YARIS CROSS HYBRID ACTIVE (AT) (2WD)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	M15AY079305
Chassis No.:	JTDKBAB3X0L002689
Maximum Power Output:	82.0 kW (109 bhp)
Open Market Value:	\$24,007.00
Original Registration Date:	15 Dec 2020
First Registration Date:	15 Dec 2020
Transfer Count:	1
Actual ARF Paid:	\$15,610.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2030
PARF Rebate Amount:	\$11,707.00

Intended COE Rebate Details

COE Expiry Date:	14 Dec 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,714.00
COE Rebate Amount:	\$25,305.00
Total Rebate Amount:	\$37,012.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 26 Sep 2024

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	25/09/2024 17:32 (SGT)
Reported by	Actual Driver
Date of Accident	25/09/2024 11:10 (SGT)
Exact Location of Accident	Boon Lay, Singapore
Additional Location Information	Tradehub 21 (Boonlay way)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMW8620H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Royale Rental Pte Ltd
Company Reg No	202337895N
Email Address	charlottevehicles@gmail.com
Mobile Phone No	(Phone) +65-96971707
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Yaris
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1500
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5141884938

DRIVER

Name of Driver	KENNY LAW YI XUN
NRIC No	S8723460F
Date Of Birth	07/08/1987
Occupation	Outdoor
Driving Pass Date	04/11/2010
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	13 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96867568
Alt. Phone Number	-
Email Address	charlottevehicles@gmail.com
Address	BLK 625 BUKIT BATOK CENTRAL 07-614 SINGAPORE 650625
Address complement	07-614
Postcode	650625
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	Unnamed
Gender	Male

PASSENGER 2

Name	Unnamed
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT



Refer to police report.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB1183T
Vehicle Manufacturer	MG
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	Ong Chuan Guan
NRIC No	S7110776J
Contact Number	(Phone) +65-96867568
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	KENNY LAW YI XUN
Gender	Male
Phone No	(Phone) +65-96867568
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	Muscle ache
Injured person in which vehicle?	SMW8620H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstance of the Accident

1110 hrs

On 25th Sep 2024, was outside junction of Tradehub21 along Boon Lay way towards Clementi. As traffic is red in colour, i stop ad waited. Suddenly a vehicle (taxi) SHB 1183T came from the back and hit onto my vehicle.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

25/09/2024

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



v2Jun2022

1



**SINGAPORE
POLICE FORCE**



T/20240925/7062

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

1 of 3

Report No. T/20240925/7062

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/09/2024 15:16		Vide Report No.: J/20240925/7050		Station Diary No.:
Informant's Particulars				
Name of Informant: Kenny Law Yi Xun		Address: 625 Bukit Batok Central #07-614 SINGAPORE 650625		
ID Type / ID No.: NRIC NO / S8723460F		Contact No.: Home/Office: Mobile: 96867568		
Nationality: SINGAPORE CITIZEN		Email: lawkenny0708@gmail.com		
Sex: Male	Age: 37	Date of Birth: 07/08/1987	Type of Informant: Driver	
Race: Chinese		Language: English		
Occupation: Private-hire car driver		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/09/2024 11:00	Type of Location: X-Junction
Location: BOON LAY WAY				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMW8620H	Motor car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20240925/7062

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20240925/7062

CONTINUATION OF REPORT

Driver			
Name	Kenny Law Yi Xun	ID No.	S8723460F
Related Vehicle	SMW8620H (Motor car)	Contact No.	96867568
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	Slight

Brief Details.

On 25/09/2024 at 1110hrs along boon lay way (outside of tradehub21) towards clementi , i was driving my vehicle (SMW 8620H) while waiting for the traffic light to turn green at the junction , suddenly a taxi (SHB 1183 T) hit my vehicle from the back . We both got down vehicle and exchange particulars



**SINGAPORE
POLICE FORCE**



T/20240925/7062

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20240925/7062

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
FAHKRUL RAZI BIN SUHAIME
Contact No.: 65476404

Signature Of Informant:
The identity of the person making this report has been
authenticated by Singpass. No signature is required.

Date/Time:
25/09/2024 15:16

Classification Of Case:

NP168

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMW8620H

Make & Model: Toyota Yaris Cross

Chassis number: JTDKBAB3X0L002689

No.	Description of spare parts	Qty	Amount S\$	
1	Tailgate <i>Dented</i>	1	\$ 2,175.40	1405
2	Tailgate windscreen glass rubber moulding <i>new</i>	1	\$ 38.90	✓
3	Tailgate "Yaris Cross" emblem <i>new</i>	1	\$ 63.40	✓
4	Tailgate centre emblem <i>new</i>	1	\$ 56.70	+
5	Tailgate "Hybrid" emblem <i>new</i>	1	\$ 83.40	✓
6	Tailgate centre lamp <i>new</i>	1	\$ 609.80	+
7	Tailgate lock <i>Dented</i>	1	\$ 647.10	415
8	Tailgate lock catch <i>new</i>	1	\$ 66.70	+
9	Tailgate inner trim board <i>Cracked</i>	1	\$ 743.20	✓
10	Tailgate inner trim board clips <i>in</i>	1set	\$ 70.00	30
11	Tailgate RH lamp <i>new</i>	1	\$ 514.80	+
12	Tailgate LH lamp <i>new</i>	1	\$ 514.80	+
13	Tailgate wiper motor <i>new</i>	1	\$ 677.30	+
14	Rear bumper (upper) <i>Dented</i>	1	\$ 444.00	✓
15	Rear bumper (lower) <i>Dented</i>	1	\$ 766.70	✓
16	Rear bumper RH reflector <i>new</i>	1	\$ 83.40	+
17	Rear bumper LH reflector <i>new</i>	1	\$ 83.40	+
18	Rear bumper RH side reverse sensor <i>new</i>	1	\$ 503.90	+
19	Rear bumper RH side reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
20	Rear bumper RH reverse sensor <i>Dented</i>	1	\$ 503.90	260
21	Rear bumper RH reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
22	Rear bumper LH reverse sensor <i>Dented</i>	1	\$ 503.90	260
23	Rear bumper LH reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
24	Rear bumper LH side reverse sensor <i>new</i>	1	\$ 503.90	+
25	Rear bumper LH side reverse sensor lock clips <i>new</i>	1	\$ 55.20	+
26	Rear bumper RH side retainer <i>new</i>	1	\$ 153.50	+
27	Rear bumper LH side retainer <i>new</i>	1	\$ 153.50	+
28	End panel <i>Dented</i>	1	\$ 1,058.90	885
29	End panel inner garnish <i>Dented</i>	1	\$ 440.10	✓
30	End panel inner garnish clips <i>new</i>	1set	\$ 70.00	30
31	RH taillamp assy <i>new</i>	1	\$ 679.40	+
32	RH taillamp gasket <i>new</i>	1	\$ 88.90	+
33	RH taillamp panel <i>new</i>	1	\$ 201.20	+
34	RH taillamp lock clips <i>new</i>	1set	\$ 50.00	+
35	LH taillamp assy <i>new</i>	1	\$ 679.40	+
36	LH taillamp gasket <i>new</i>	1	\$ 88.90	+
37	LH taillamp panel <i>new</i>	1	\$ 201.20	+
38	LH taillamp lock clips <i>new</i>	1set	\$ 50.00	+

39	Rear antenna sensor <i>could</i>	1	\$	100.00	✓
40	Rear compartment panel board <i>Detent</i>	1	\$	557.80	✓
41	Spare tyre sponge <i>new</i>	1	\$	129.10	+
42	Rear RH fender inner trim board	1	\$	829.80	+
43	Rear RH fender inner trim board clips <i>new</i>	1set	\$	70.00	+
44	Rear LH fender inner trim board <i>new</i>	1	\$	829.80	+
45	Rear LH fender inner trim board clips	1set	\$	70.00	+
46	Exhaust silencer <i>new</i>	1	\$	1,502.30	+
47	Exhaust silencer gasket	1	\$	66.80	+

\$ 17,946.00
 Parts less 25% \$ 4,486.50
 Total: \$ 13,459.50

No.	Special Nett Items	Qty	Amount S\$	
1	Tailgate windscreen glass sealant <i>new</i>	1	\$ 80.00	40
2	Tailgate windscreen glass inner seal	1	\$ 60.00	30
3	Tailgate reverse camera <i>new</i>	1	\$ 680.00	+
4	End panel joint sealant <i>new</i>	1	\$ 80.00	60

Total: \$ 900.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,800.00	700.80
2	Spray painting on affected areas and panels	\$ 1,600.00	600.00 800
3	Check wiring and lighting system on affected areas	\$ 80.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	60
5	Remove and replace tailgate windscreen glass to assist repair	\$ 220.00	120
6	Remove and replace tailgate reverse camera to assist repair	\$ 100.00	50
7	Remove and replace tailgate inner mechanism to new tailgate	\$ 120.00	60

8	Remove and replace rear bumper reverse sensors	\$ 80.00	50
9	Remove and replace rear inner trims and garnish to assist repair	\$ 380.00	60
10	Remove and replace exhaust silencer and gasket to assist repair	\$ 180.00	4

Total: \$ 2,860.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 13,459.50

Special Nett: \$ 900.00

Labour: \$ 2,860.00

Total: \$ 17,219.50

Adrian King
1/s 27/09/20

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____