

REF:CS1/LAW24090500/Eqp3 (SKC 7576M)

Special Instruction:

ASSIGNMENT (Office)

From (Person): HENG XINYI
(SEAH ONG) of HSBC Date/Time: 24/09/2024

Estimated Cost: _____ Bill to: _____

L/SUM : 9700 / REPAIR : 7 DAYS

Third Parties:

Claimant: ~~ALL IN AUTOMOTIVE~~
Surveyor: APPRAISER

Workshop: SAT (SG) PTE LTD

OD/TP Re-inspection **Evaluation**

To Inspect Vehicle No: SKC 7576M Insured: SMC 3791K

at Workshop m/s SAT (SG) PTE LTD
of 61 UBI ROAD 1 #01-14 OXLEY BIZHUB

Policy No: 24.32098

Claim No: S9M023N5

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12/10/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red \$____/____%; Original ____ days)

Date/Time: 30/09/24 Submit ~~Final Fig~~ LS \$4300, 4 days (Red \$ 5400 / 56 %; Original 7 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 30/09/24 File Pass to Typist

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to