

REF: CS/SMR24090506/Avp3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: \_\_\_\_\_

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: \_\_\_\_\_

at Work \_\_\_\_\_

of \_\_\_\_\_

Insured: **SG 6293U**

Policy No \_\_\_\_\_

Claims No **BUS/09/24/8028**

Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh \_\_\_\_\_

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SLT4078C** Yr Regn: **2017 Oct**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Kia Carens** C.C. **1685**

Colour: **Grey.** A/C: Insured / Std / NI / NA

Sp. Reading: **362043** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **KNAHU815VJ7192774.**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/45R17.**

R: **215/45R17.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

**Medallion**

Front Rear

R/Bal. **06** mm R/Bal. **06** mm

L/Bal. **06** mm L/Bal. **06** mm

D.O.A. **24/9/2024** D.O.I. **25/09/24**

Survey held at **AIF**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**Rear o/s.**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>TP Smart</b>
<b>31/10/24</b>	<b>Adrian confirmed LS \$7200 (red 13,676.07, 65%)</b>
	<b>COE Expiry</b>
	<b>Estimate given during 1st Survey: Yes ( ) No ( )</b>
	<b>MV: 47K</b>
	<b>PV: 27K</b>
	<b>Nett: 20K</b>
	<b>159R</b>

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

\_\_\_\_\_

Days Of Repair: **8**

Resurvey No. of Trip: \_\_\_\_\_

Addl Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Inve (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 + R.S. \$1 \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_
