

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL		Ref:	CS/AGI24090524/Rqp3e2	
	(BUDGET DIRECT INSURANCE)		Date:	30/09/2024	
	190 CLEMENCEAU	AVENUE #03-01 PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	SINGAR OILE SHOP	Policy Particulars :- THIRD PARTY CLAIM			
1.	Insured Veh.	SMW 8381Y	Veh. Inspected	SLK 6347K	
	Policy No.	P10514422R03	Coverage	0	
	Claim No.	C10031855/MC	Excess	\$0.00	
	Assign From	MONICA CHUNG	Assign Date	30/09/2024	
2.	A33igii i ioiii	Vehicle		00/00/2024	
<u> </u>	Make & Model	HONDA VEZEL HYBRID 1.5X A	c.c	1496	
	Engine No.	LEB5917160	Year of Reg.	23/01/2017	
	Chassis No.	RU31217145	Colour	GREY	
	Odometer	473222 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM	•		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60 R16	RYDANZ	6	
	L/H Front Tyre	215/60 R16	RYDANZ	6	
	R/H Rear Tyre	215/60 R16	RYDANZ	6	
	L/H Rear Tyre	215/60 R16	RYDANZ	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	22/09/2024	Inspection Date	01/10/2024	
	Survey held at	urvey held at LION CITY RENTALS PTE LTD - 4 JALAN BESUT, SINGAPORE 619557			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Day			
FOTIMATED MODIMAL DEDICE FOR DEDAID, F. Marking Device					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days