



1 of 3

Report No. T/20240926/2102

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Date/Time Report Made: 26/09/2024 19:42			Vide Report No.:	Station Diary No.	
Informa	nt's Particu	llars			
Name of Informant: Chai Luo Wei			Address: APT BLK 104B DEPOT ROAD #13-557 DEPOT HEIGHTS SINGAPORE 102104		
ID Type / ID No.: FIN NO / M3069616J			Contact No.: Home/Office:	Mobile: 85877118	
Nationality: MALAYSIAN		1.00	Email:		
Sex: Male	Age:	Date of Birth: 22/01/2000	Type of Informant: Rider		
Race: Chinese			Language:		
Occupation: SHENG SHIONG WORKER			Driving Licence Information: Class: 2B	Date of Expiry: 22/01/2029	

Seneral Information Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 26/09/2024 14:40	Type of Location Straight Road
Location: TELOK BLAN Lamp Post N Weather:	NGAH CRESCENT	Road Surface:		
Sunny Traffic Flow: One Way		Dry Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Colli	sion: ving Vehicles - Side Swi			Anyone conveyed by ambulance: No

	ehicle Involve		Model	Color	Conditio	No of Passenge
Vehicle No.	Туре	Make	Model	Color	Slightly	1
SHB1020E	Motor car				Damaged	
					Slightly	1
VKM680	Motorcycle				Damaged	





2 of 3

Report No. T/20240926/2102

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Brief Details.

I am here to lodge a police report to claim for insurance purposes.

As I was riding my motorcycle (VKM680) along Henderson Road on the second lane, I was sideswiped by a maroon taxi (SHB1020E). As he was switching into my lane, he did not signal. Thus, there was not enough time for me to avoid him. Hence, the left side of the taxi knocked into me, and I fell off my motorcycle.

I suffered the following injuries:

Cuts on my both knuckles, right forearm and on my left thigh. Abrasion on my left elbow.

My motorcycle also had been damaged from the accident. Both side mirror of my motorcycle broke off, IU unit, engine leaked (causing black oil spillage), scratches on the front bonnet and scratches on part of the body kit.

That is all.





3 of 3

Report No. T/20240926/2102

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Signature of Officer Recording A / SCCPL OOI YI ZHE	The
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case:	
TP / AEIT / SR STAFF SGT FAHKRUL R/ Contact No.: 65476404	AZI BIN SUHAIME

Signature Of Informant:	
	16
Date/Time: 26/09/2024 19:42	
Classification Of Case:	