

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile						
	MS FIRST CAPITA	L INSURANCE LTD	R	ef:	CS/FCI24100001/Unp3m4(N)	
	16 RAFFLES QUA #42-01 HONG LEC 048581	Y DNG BUILDINGSINGAPORE	Di	ate:	07/10/2025	
	ATTN: SERENE		C	ode:	FCI2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHA 4339Y	Veh. Inspected		NCS 1642	
	Policy No.	D-24101861MFCT	Coverage (\$)		0.00	
	Claim No.	D24003512MFCT	Excess (\$)		0.00	
	Assign From	AINI BINTE	Assign Date		30/09/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MODENAS KRISS MN100F	c.c		97	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	PMNMN100FDML22359	Colour		RED / WHITE	
	Odometer	60584 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70-90-17	VIVA		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80-90-17	VIVA		6 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION AND O/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	17/04/2024	Inspection Date		01/10/2024	
	Survey held at EROFIA MOTOR TRADING PTE LTD					
		1 KAKI BUKIT AVENUE 6				
		#02-62 SINGAPORE 417883				
5a.	. Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					