

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III24100003/EVP3M4
Date: 07/10/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0009399_01
Claimant Vehicle No : FZ6168C Insured Vehicle No : GBM2523C
Date of Loss: 25/08/2024 Nature of Claim: TP Claim No: MFL2024D0010045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FZ6168C
Make & Model: HONDA WAVE 125R, 125cc NF125MP Engine No: NF125MPE0057466
Reg. Date: 02/09/2005 (Man. Year: 2005) Chassis No: NF125MP0057466
Colour: Purple Odometer: 9319 km
Engine Capacity: 125 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17
Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/09/2024
Date Inspected: 30/09/2024 Inspected At: EQBH PTE LTD
25 KAKI BUKIT ROAD 4
#03-79 SYNERGY @ KB
SINGAPORE 417800
Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Oct 2024)	
Parts:	N/A	HONDA WAVE 125R 125cc NF125MP (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FZ6168C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >