

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	ale Des Experts En	Automobile
MS	LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24100007/Knh3m4
	ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Date:	10/10/2024
			Code:	LIP
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SKV 9586X	Veh. Inspected	SMF 8691S
	Policy No.	-	Coverage	0
	Claim No.	AVS24/2993	Excess	\$0.00
	Assign From	ANDY SEAH	Assign Date	30/09/2024
2.	Vehicle Details			
	Make & Model	AUDI Q2 1.0 TFSI (A)	C.C	999
	Engine No.	CHZ418736	Year of Reg.	12/06/2018
	Chassis No.	WAUZZZGA6JA064570	Colour	METALLIC SILVER
	Odometer	108830 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	215/60R16	BRIDGESTONE	7
i	L/H Front Tyre	215/60R16	BRIDGESTONE	7
ļ				
	R/H Rear Tyre	215/60R16	BRIDGESTONE	6
	R/H Rear Tyre L/H Rear Tyre	215/60R16 215/60R16	BRIDGESTONE BRIDGESTONE	6 6
4.	L/H Rear Tyre	215/60R16  Description	BRIDGESTONE	
	L/H Rear Tyre	215/60R16	BRIDGESTONE	
THE	L/H Rear Tyre	215/60R16  Description  NED DAMAGES AT REAR PORTION.	BRIDGESTONE	
THE	L/H Rear Tyre  VEHICLE SUSTAIN	215/60R16  Description  NED DAMAGES AT REAR PORTION.	BRIDGESTONE of Damages	
THE	L/H Rear Tyre  VEHICLE SUSTAIN  AGES SEE DETAIL  Accident Date	215/60R16  Description NED DAMAGES AT REAR PORTION. S.  General In 25/09/2024	BRIDGESTONE of Damages  formation Inspection Date	01/10/2024
THE	L/H Rear Tyre  VEHICLE SUSTAIN MAGES SEE DETAIL	215/60R16  Description NED DAMAGES AT REAR PORTION. S.  General In 25/09/2024	BRIDGESTONE of Damages  formation Inspection Date 2A #03-12 AUTOPAI	6
THE	L/H Rear Tyre  VEHICLE SUSTAIN  AGES SEE DETAIL  Accident Date	215/60R16  Description NED DAMAGES AT REAR PORTION. S.  General In 25/09/2024  10 ANG MO KIO INDUSTRIAL PARK	BRIDGESTONE of Damages  Iformation Inspection Date 2A #03-12 AUTOPAI ELTD	01/10/2024
THE DAN <b>5. 5a.</b> A) T	L/H Rear Tyre  VEHICLE SUSTAIN  MAGES SEE DETAIL  Accident Date  Survey held at  HE INSPECTION W	215/60R16  Description NED DAMAGES AT REAR PORTION. S.  General In 25/09/2024  10 ANG MO KIO INDUSTRIAL PARK REPAIRER: JD MOTORSPORTS PTE	BRIDGESTONE  of Damages  Iformation  Inspection Date  2A #03-12 AUTOPAI  LTD  arks  EJUDICE" BASIS.	01/10/2024 NT BUILDING SINGAPORE 568407 –

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days