

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	LIBERTY INSURAN		Ref:	CS/LIP24100010/Rqh3m4
IVIO	ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Date:	25/11/2024
			Code:	LIP
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	PC 3592H	Veh. Inspected	SNQ 8996T
	Policy No.	-	Coverage	0
	Claim No.	BVS24/0704	Excess	\$0.00
	Assign From	SAM	Assign Date	30/09/2024
2. Vehicle Details				
	Make & Model	HONDA STEPWAGON SPADA 2.0	C.C	1993
	Engine No.	LFA2225657	Year of Reg.	21/03/2024
	Chassis No.	RP81035647	Colour	BLUE
	Odometer	9308 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	FAIR
	Modification(s)	RIMS: SPORTS RIM		
3.		Conditions of Tyres		
		Size	Make	Balance (mm)
	l	225/45 R18	CONTINENTAL	6
	R/H Front Tyre	=======================================		
	R/H Front Tyre L/H Front Tyre	225/45 R18	CONTINENTAL	6
			CONTINENTAL CONTINENTAL	6 6
	L/H Front Tyre	225/45 R18		
4.	L/H Front Tyre R/H Rear Tyre	225/45 R18 225/45 R18	CONTINENTAL CONTINENTAL	6
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/45 R18 225/45 R18 225/45 R18	CONTINENTAL CONTINENTAL of Damages	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/45 R18 225/45 R18 225/45 R18  Description of ED DAMAGES AT THE O/S REAR POR	CONTINENTAL CONTINENTAL of Damages	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	225/45 R18 225/45 R18 225/45 R18  Description of ED DAMAGES AT THE O/S REAR POR	CONTINENTAL CONTINENTAL of Damages RTION.	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	225/45 R18 225/45 R18 225/45 R18  Description of ED DAMAGES AT THE O/S REAR PORES.	CONTINENTAL CONTINENTAL of Damages RTION.	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  EVEHICLE SUSTAIN MAGES SEE DETAIL	225/45 R18 225/45 R18 225/45 R18  Description of the DAMAGES AT THE O/S REAR PORTS.  General Inc.	CONTINENTAL CONTINENTAL OF Damages RTION.  formation Inspection Date	6 6 01/10/2024
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN AGES SEE DETAIL	225/45 R18 225/45 R18 225/45 R18  Description of ED DAMAGES AT THE O/S REAR PORTS.  General Interpretation of Education (Control of	CONTINENTAL CONTINENTAL Of Damages RTION.  formation Inspection Date ON LEE STREET #0	6 6 01/10/2024
THE DAM  5.  5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  EVEHICLE SUSTAIN MAGES SEE DETAILS  Accident Date Survey held at  HE INSPECTION WA	225/45 R18 225/45 R18 225/45 R18  Description of ED DAMAGES AT THE O/S REAR POFES.  General Interpretation of Edition of	CONTINENTAL CONTIN	6 6 01/10/2024 1-60 PIONEER POINT, SINGPORE

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days