



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24100011/Uvh3e2(N)

75 BRAS BASAH ROAD INCOME CENTRE
SINGAPORE 189557

Date: 20/01/2025

ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGP 9061Y	Veh. Inspected	SLC 2528Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1297528-001	Excess (\$)	0.00
Assign From	HELENA TAN	Assign Date	01/10/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11112319	Colour	BLUE
Odometer	-	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	TRIANGLE	5 mm
L/H Front Tyre	215/60 R16	TRIANGLE	5 mm
R/H Rear Tyre	215/60 R16	KAPSEN	5 mm
L/H Rear Tyre	215/60 R16	KAPSEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S, O/S REAR PORTION AND O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/09/2024	Inspect Date / Time	01/10/2024 (11:44 AM)
Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	18 Working Days
-------------------------------------	-----------------