

ASS. REC. BY: Tajm

REF: CS/1M/24/00013/typ3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: limts

Vehicle: IN / OUT

Veh No: SHA 7915 P Yr Regn: 2024 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 57137 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD AE 3 AY 803 002506

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 01/10/24

Survey held at Comfort Legacy

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/G / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

Drawn & Forwarded:

☐ : Prel. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CP/P

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/09/2024
Vehicle Reg. No.:	SHA7915P	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	31/05/2024
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2X51751	Chassis No:	JTDAE3AU803002506
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,219.80
Miscellaneous Items	12.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,051.80
+ GST 9.00% (S\$)	184.66
Nett Amount (S\$)	2,236.46

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

1/10 @ 10:40hrs.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2024) Lim Tien Siong
Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA7915P/01/10/2024 10:40
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	de *655.60 FL
2	1		*REAR BUMPER CTR COVER	25.00	0.00	de *541.70 FL
3	10		*REAR BUMPER CLIPS	25.00	0.00	re *22.00 FL
4	1		*REAR BUMPER BACK UP LAMP LH	25.00	0.00	x *298.90 FL
5	1		*REAR BUMPER ULTRA SENSORS	25.00	0.00	x *108.20 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	1,626.40
- List Item Discount on L Items (S\$)	406.60
Total Parts (S\$)	1,219.80

ComfortDelGro Engineering Pte Ltd/SHA7915P/01/10/2024 10:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Lim Tien Siong

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)			12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	380	400.00
2	SPRAY PAINTING	New	280	300.00
3	R/I REVERSE ULTRA SENSORS	New	30	120.00
Gross Labour Cost (S\$)				820.00

ComfortDelGro Engineering Pte Ltd/SHA7915P/01/10/2024 10:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

tanphn 97495749
wp' 1/10/24 3pm
p/p Resurvey before paint
2 days
tanphn c l h k a n d o . c m

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Job: ARC Repair TP(CLSO)1
Customer: COMER

JOB CARD Sales Order: 5955995 JC NO305605622

Customer: COMFORT TRANSPORTATION PTE LTD
Customer No. 7010045
Address: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)

REGN NO: SHA7915P	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL TOY PRIUS HYBRID30	DATE/TIME IN 09.2024 16:00
YR OF MANU. 31.05.2024	TARGET DATE
CHASSIS CODE JTDAE3AU803002506	COMPLETION DATE/TIME:


Amount Card No.

Accident Date: 29.09.2024
Accident Time: 3P 29.09.2024

JOB DESCRIPTION

Job No: 00010
Labor Code: PB

DESCRIPTION
LUMP SUM REPAIR-SHA7915P-TP



Vehicle Returned & PASSED OUT BY: _____

Signature of SERVICE ADVISOR

Signature of CUSTOMER'S SIGNATURE

Checklist Item: edgement Slip

Checklist Item: Exit Pass

Vehicle No.: SHA7915P LIMITS

Vehicle No.: SHA7915P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard