

ASS. REC. BY:

REF:

0021

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No 2nd parts available, rec. order over sea.

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

S + RS. SI

: F.P.M.S

: Others

Report Format:

ump Sum / I.B.I. (\$

TOTAL



# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0035742  
United Overseas Insurance Ltd  
146 Robinson Road  
#02-01 UOI Building  
Singapore 068909

Page ..... 1 of 2  
Your ref. .... DHOM110167111905  
Job No. .... 74715  
Our ref. .... 24.09.17  
Payment .....  
Date ..... 30/9/2024

Attn .....

Vehicle No .... SLX 7628A  
Vehicle Model : Volkswagen Passat  
Accident on ... 14/9/2024

*Not Withenw*  
*Resurvey Bepaint*  
*Ex \$500/ 5days*

| Quantity                                   | Unit | Description                        | Unit price | Disc. pct. | Amount               |
|--|------|------------------------------------|------------|------------|----------------------|
| Supply of Parts:                           |      |                                    |            |            |                      |
| 1.00                                       | Pc   | Rear fender RH                     | 1,510.00   |            | <i>Bz</i> 1,510.00 ✓ |
| 1.00                                       | Pc   | Rear fender air vent RH            | 45.00      |            | 45.00 ✓              |
| 1.00                                       | Pc   | Rear bumper                        | 925.00     |            | <i>Bu</i> 925.00 ✓   |
| 1.00                                       | Pc   | Rear bumper outer retainer RH      | 60.00      |            | <i>on</i> 60.00 ✓    |
| Total amount of parts supplied-S\$2,540.00 |      |                                    |            |            |                      |
| 1.00                                       |      | 10% of parts supplied:             | 254.00     |            | 254.00               |
| Special nett item:                         |      |                                    |            |            |                      |
| 1.00                                       | Pc   | Rear windscreen inner seal         | 30.00      |            | <i>nc</i> 30.00 ✓    |
| Labour & Misc:                             |      |                                    |            |            |                      |
| 1.00                                       |      | To dismantle+refix rear windscreen | 160.00     |            | 160.00 <i>1201</i>   |
| 1.00                                       |      | To supply sealant                  | 40.00      |            | 40.00 ✓              |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。  
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



来發 ( 明 記 ) 摩 哆 有 限 公 司  
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

ESTIMATE

EST. No ..... EST0035742  
United Overseas Insurance Ltd  
146 Robinson Road  
#02-01 UOI Building  
Singapore 068909

Page ..... 2 of 2  
Your ref. .... DHOM110167111905  
Job No. .... 74715  
Our ref. .... 24.09.17  
Payment .....  
Date ..... 30/9/2024

Attn .....

Vehicle No .... SLX 7628A  
Vehicle Model : Volkswagen Passat  
Accident on ... 14/9/2024

| Quantity | Unit | Description  | Unit price | Disc. pct. | Amount     |
|----------|------|--|------------|------------|------------|
| 1.00     |      | To check/clear fault codes after repair  | 120.00     |            | 120.00 ?   |
| 1.00     |      | To dismantle+refix rear seat assy, rear speaker board+rear fender inner trim RH, etc | 160.00     |            | 160.00 120 |
| 1.00     |      | To cut+weld, to knock dents on rear fender inner panel RH and renew parts            | 800.00     |            | 800.00 650 |
| 1.00     |      | To spray paint   | 800.00     |            | 800.00 600 |

Sub-Total 4,904.00  
GST 9.00% 441.36  
Total S\$ 5,345.36

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。  
，还有先进的 SAICO Deluxe 喷漆烘炉。  
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support  
ly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO  
uxe oven heater for re-spraying all motor vehicles."



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                                     |
|---------------------------------|-------------------------------------|
| Date of First Submission        | 16/09/2024 15:04 (SGT)              |
| Reported by                     | Both Policyholder and Actual Driver |
| Date of Accident                | 14/09/2024 14:30 (SGT)              |
| Exact Location of Accident      | Ang Mo Kio Ave 5, Singapore         |
| Additional Location Information | turning to Ang Mo Kio Avenue 2      |
| Country/State of Loss           | Singapore                           |

### DETAILS OF OWN VEHICLE

|                             |                             |
|-----------------------------|-----------------------------|
| Vehicle Registration Number | SLX7628A                    |
| INSURED/POLICYHOLDER        |                             |
| Is company?                 | No                          |
| Name Of Registered Owner    | Lee Yoke Chong              |
| NRIC No                     | SXXX588D                    |
| Email Address               | leeyokechong.1956@gmail.com |
| Mobile Phone No             | (Phone) +65-97572166        |
| Alternative Phone No        | -                           |


### VEHICLE PARTICULARS

|  |             |
|--|-------------|
| Manufacturer   | Volkswagen  |
| Model  | Passat      |
| Variant  | -           |
| Exact purpose for which vehicle was being used at time of accident           | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes         |
| Vehicle Category   | Private car |
| Transmission   | Auto        |
| CC   | 1800        |
| Vehicle Fuel   | -           |
| First Registration Date  | -           |
| Chassis no   | -           |
| Effective Date/Time of Ownership   | -           |

### INSURANCE COMPANY

|                                   |                               |
|-----------------------------------|-------------------------------|
| Name of Insurance Company         | United Overseas Insurance Ltd |
| Policy Number / Cover Note Number | DHOM110167111905              |

DRIVER



Lee Yoke Chong



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

588D

### Vehicle Details

Vehicle No.:

SLX7628A

Vehicle to be Exported:

Yes

Intended Deregistration Date:

16 Sep 2024

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

PASSAT B8 1.8 TFSI AT SR NAV 17W 3G24JZ

Primary Colour:

Brown

Manufacturing Year:

2018

Engine No.:

CJS261537

Chassis No.:

WVWZZZ3CZJE151879

Maximum Power Output:

132.0 kW (177 bhp)

Open Market Value:

\$32,128.00

Original Registration Date:

10 Apr 2018

First Registration Date:

10 Apr 2018

Transfer Count:

0

Actual ARF Paid:

\$36,980.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

09 Apr 2028

PARF Rebate Amount:

\$24,037.00

### Intended COE Rebate Details

COE Expiry Date:

09 Apr 2028

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$37,605.00

COE Rebate Amount:

\$13,407.00

Total Rebate Amount:

\$37,444.00

### Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your

The information contained herein is correct as at 16 Sep 2024

OK