



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100017/Uqh3
75 BRAS BASAH ROAD	Date:	17/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFA 1322M	Veh. Inspected	SMD 1676T
Policy No.	-	Coverage	0
Claim No.	MT/1297501-002	Excess	\$0.00
Assign From	ENG HUEY HUEY	Assign Date	01/10/2024

### 2. Vehicle Details

Make & Model	HONDA CITY 1.5 SV CVT	C.C	1497
Engine No.	L15Z16202581	Year of Reg.	06/08/2018
Chassis No.	MRHGM6660KT000328	Colour	RED
Odometer	39295 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/55R16	BRIDGESTONE	6
L/H Front Tyre	185/55R16	BRIDGESTONE	6
R/H Rear Tyre	185/55R16	BRIDGESTONE	6
L/H Rear Tyre	185/55R16	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	29/09/2024	Inspection Date	01/10/2024 (11:32)
Survey held at	15 KAKI BUKIT ROAD 4, #01-53, SINGAPORE 417808 – REPAIRER: ZOOM AUTOWERKS PTE LTD		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days