

ASS. REC. BY: Taufik REF: CS/TM/24/00044/Tvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SNJ 775D

Policy No. MZC05842

Claims No. M2405714

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chiauey

Vehicle: IN / OUT

Veh No: SHC 1499C Yr Regn: 2018, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Trax / Prime Mover /

Truck / Traller or

Make: Hyundai Ioniq c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 524572 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB51CVR4107526

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: III / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WEST LAKE

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm L/Bal. 6 mm

L/Bal. 6 mm U/Bal. 6 mm

D.O.A. 1/10/2024 D.O.I. 02/10/24

Survey held at Comfort Lorry

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Frt o/s

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/10/24	Taufik confirmed LS \$2800 (red 1155.04, 29%)

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

\$ + RS. SI

Add Fee: ☐ : Site Insp (\$

1)

Date/Time, File Return to?

2)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/10/2024
Vehicle Reg. No.:	SHC1499C	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Vehicle Reg. Date:	13/09/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU081777	Chassis No:	KMHC851CVKU107526
Odometer:	524572 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,583.04
Miscellaneous Items	12.00
Labour	1,360.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,955.04
+ GST 9.00% (\$\$)	355.95
Nett Amount (\$\$)	4,310.99

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 02 Oct 2024)**Parts:** N/A HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC1499C/02/10/2024 08:32**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00	de ✓ *481.10 FL
2	1		*FRONT BUMPER BRACKET /RH	20.00	0.00	✗ *55.80 FL
3	1		*FRONT BUMPER UPPER MOULDING	20.00	0.00	aut ✓ *368.50 FL
4	1		*FRONT FENDER EMBLEM	20.00	0.00	ref ✓ *26.60 FL
5	1		*HEAD LAMP RH	20.00	0.00	aut ✓ *2,110.30 FL
6	1		*FRONT BUMPER GRILLE RH	20.00	0.00	aut ✓ *186.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,228.80
- List Item Discount on L Items (S\$)	645.76
Total Parts (S\$)	2,583.04

ComfortDelGro Engineering Pte Ltd/SHC1499C/02/10/2024 08:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	12.00
Sub Total (\$\$)			12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	380	700.00
2	SPRAY PAINTING	New	560	600.00
3	CHECK LIGHTING AND WIRING	New	30	60.00
Gross Labour Cost (\$\$)				1,360.00

ComfortDelGro Engineering Pte Ltd/SHC1499C/02/10/2024 08:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjihi 97495749
'wp' 2/10/24 05pm
c/s Masay after repair
tanjihi c/hhanton
02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 01.10.2024 16:21

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5956088

JC NO305605706

CUSTOMER

REGN NO.:

SHC1499C

MILEAGE

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD

MAKE:

HYUNDAI

FUEL

CUSTOMER NO. 7010045

E.....1/2.....F

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

MODEL

IONIQ(G2)

DATE/TIME IN
01.10.2024 13:10

L (R) 65508755

(O)

YR OF MANU.

13.09.2018

TARGET DATE

(P)

CHASSIS CODE

KMHC851CVKU107526

COMPLETION DATE/TIME:


SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 01.10.2024

NATURE: 3P 01.10.2024

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC1499C CHIANG

Vehicle No.: SHC1499C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard