

ASS. REC. BY: Taufik REF: CS/TM/24/00044/Tvp3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chiauey Vehicle: IN / OUT

Veh No: SHC 1499C Yr Regn: 2018, 09
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /
 Truck / Traller or
 Make: Hyundai Ioniq c.c. 1580
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 524572 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHCB51CVR4107526
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: III / S/Rlm / STD A/Rlm or
 Tyre Size: F: 195/65R15
 R: 27
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 02/00/24
 Survey held at Comfort Lorry
 Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or
Frt o/s
 The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
 1) ☐ : Final Report
 Date/Time, File Return to? _____
 2) _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$ _____)
 Survey Fee: _____
 Transportation: _____
 \$ + RS. SI

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/10/2024
Vehicle Reg. No.:	SHC1499C	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Vehicle Reg. Date:	13/09/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU081777	Chassis No:	KMHC851CVKU107526
Odometer:	524572 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,583.04
Miscellaneous Items	12.00
Labour	1,360.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,955.04
+ GST 9.00% (\$\$)	355.95
Nett Amount (\$\$)	4,310.99

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 02 Oct 2024)

Parts: N/A HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1499C/02/10/2024 08:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00	de ✓ *481.10 FL
2	1		*FRONT BUMPER BRACKET /RH	20.00	0.00	✗ *55.80 FL
3	1		*FRONT BUMPER UPPER MOULDING	20.00	0.00	aut ✓ *368.50 FL
4	1		*FRONT FENDER EMBLEM	20.00	0.00	ref ✓ *26.60 FL
5	1		*HEAD LAMP RH	20.00	0.00	aut ✓ *2,110.30 FL
6	1		*FRONT BUMPER GRILLE RH	20.00	0.00	aut ✓ *186.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,228.80
- List Item Discount on L Items (S\$)	645.76
Total Parts (S\$)	2,583.04

ComfortDelGro Engineering Pte Ltd/SHC1499C/02/10/2024 08:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	12.00
Sub Total (\$\$)			12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	380	700.00
2	SPRAY PAINTING	New	560	600.00
3	CHECK LIGHTING AND WIRING	New	30	60.00
Gross Labour Cost (\$\$)				1,360.00

ComfortDelGro Engineering Pte Ltd/SHC1499C/02/10/2024 08:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjihi 97495749
 'wp' 2/10/24 05pm
 c/s Masay after repair
 Tanjihi C Khartou
 02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 01.10.2024 16:21

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5956088

JC NO305605706

CUSTOMER

REGN NO.:

SHC1499C

MILEAGE

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD

MAKE:

HYUNDAI

FUEL

CUSTOMER NO. 7010045

E.....1/2.....F

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

MODEL

IONIQ(G2)

DATE/TIME IN
01.10.2024 13:10

L (R) 65508755 (O)

YR OF MANU.

13.09.2018

TARGET DATE

(P)

CHASSIS CODE

KMH851CVKU107526

COMPLETION DATE/TIME:


SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 01.10.2024

NATURE: 3P 01.10.2024

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC1499C CHIANG

Vehicle No.: SHC1499C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard