

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
   This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of First Submission 30/09/2024 20:41 (SGT) Reported by ..... Both Policyholder and Actual Driver Date of Accident 29/09/2024 15:50 (SGT) Exact Location of Accident Singapore Additional Location Information DUNEARN ROAD Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number ET9822X Is company? ..... No Name Of Registered Owner ONG TERENCE NRIC No SXXXX724Z Email Address TERENCEONG@HOTMAIL.SG Mobile Phone No (Phone) +65-96961340 Alternative Phone No VEHICLE PARTICULARS Mazda Model ..... 2 Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to No - Claiming third party Vehicle Category ..... Private car Auto Vehicle Fuel First Regisration Date Chassis no ...... Effective Date/Time of Ownership INSURANCE COMPANY Name of Insurance Company Liberty Insurance Pte Ltd Policy Number / Cover Note Number



Name of Driver	ONG TERENCE
NRIC No	SXXXX724Z
Date Of Birth	17/06/1963
Occupation	Indoor
Driving Pass Date	29/04/1986
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience Gender	38 YEARS AND 5 MONTHS
Mobile Number	Male (Phane) LCE 00001340
Alt. Phone Number	(Phone) +65-96961340
Email Address	TERENCEONG@HOTMAIL.SG
Address	56 ST PATRICKS ROAD
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	**
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	-
modrance company of other verticle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged?	- Voo
Number of Passengers (Including Driver)	Yes 1
Has the driver been approached by unknown person(s)	1
soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	•
Translator's email	-
Original language used in the statement	-
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No .
Was notice of intended Prosecution given?	No
If yes, against whom?	-
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN	
ATTACHMENT(S)	Oren de Grande de la companya de la Performación de la companya de la c
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vohiele Degistration Number	
Vehicle Registration Number	SHA7198S
Vehicle Manufacturer	-

Venicle Model	-
Vehicle Variant	_
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	_
Contact Number	_
Address	_
Address complement	
Postcode	_
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	
No. Of Fassenger (including briver)	-

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Driver's Signature (If driver is not the policyholder) / Date Witnessed by Reporting Centre Time & Time Personnel

Sketch Plan

UNGARN RUAD

### Describe Circumstances of the Accident

ON SUNDAY 29 SEP 2024 ARHUND 3.50 PM I WAS PRIVING ALONG
ON SINDAY 29 SEP 2024 ARUND 3.50 PM, I WAS PRIVING ALONG DUNBARN ROAD TOWARD CITY. AT THE JUNCTION BETWEEN
DUNEARN RUAD AND CHANCERY LAND THE TRAFFIC LIGHT WAS
OUNEARN RUAD AND CHANCERY LAND THE TRAFFIC HATH WAS RED AND I STOPPED BEHIND TWO TO THREE CARS BEHIND THE
TRAFFIC LIGHT I WAS IN THE MIDDLE OF THREE LAWES
TRAFFIC 4GHT. I WAS IN THE MIDDLE OF THREE LAWES  A BLUE COMFORT TAXI THEN COLLIDED INTO MY CAR
I DAMAGING MY KELLE CAR RIMPBE
1 TOOK PHOTO OF THE DAMAGE AND THE TAXI.  MOVING TO CHANCERY LAND TO AVOID BLOCKING TRAFFIC.
MOVING TO CHANCERY LAND TO BUILD BLOCKING TRAFFIC
GOT THE PRIVAR'S PHONE NUMBER
·
·

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## INSURER ENQUIRY

## Find insurer

Vehicle reg. no.

SHA7198S

**Date of Accident** 

29/09/2024

Reset

## % RESULT & RECEIPT

TP Insurer Enquiry	
Insurance	MS First Capital Insurance Ltd
Period of Insurance	01/01/2024 - 31/12/2024
Requested By	TRANSEUROKARS PTE LTD - TA
Requested Date	30/09/2024 10:42


## Payment details

Request Amount: \$\$2 GST Amount: **\$\$0.18** 

Total Amount Due (GST Inclusive): \$\$2.18

## **General Insurance Association**

Records Management Centre GST Registration No: M400017735



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1579724Z



Name

ONG TERENCE



. 63

M



Date of birth 17-06-1963 Country/Place of birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

29 Apr 1986

NP 428A

Licence No: S1579724Z

6216293



NRIC No. S1579724Z



Date of issue

13-06-2019

56 ST. PATRICK'S ROAD #01-10 SINGAPORE 424171



## **QUOTATION**

CODE: CUSTOMER:

ADDRESS:

F0001

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY

#42-01 HONG LEONG BUILDING

SINGAPORE 048581

ATTN:MOTOR CLAIM DEPT

CONTACT NO.: 6507 3848 MODEL:

CHASSIS NO.: JM6DJ2HAA01200187

MAZDA2 IPM HB HIGH WHITE

ENGINE NO.: P520484407 **REG NO.:** ET9822X **REGN DATE:** 30/11/2017 PAGE NO.:

DOCUMENT NO.: DOCUMENT DATE:

1504

02/10/2024

Lee Yao Sheng

POS ID:MU

PRINTED BY:

SERVICE ADV: CSP/OP CODE:

Lee Yao Sheng

DEPT: WIP NO .:

20732

REF. NO .: DATE IN: EXT. WTY:

MILEAGE:

0

### **DESCRIPTION:**

Item	Description	Stk/Status Qty. Unit Price	Gross amount (	
		SGD	SGD	
NOTES	MS FIRST CAPITAL TP CLAIM		0.00	0
SUB	to remove & replace rear bumper, end		4,752.00	S
	PANEL & REAR FENDER LOWER PANEL LH.			
	AND ALL ACCIDENT AFFECTED AREA.			
SUB	to respray rear bumper, end panel &		3,780.00	S
	REAR FENDER LOWER PANEL LH.			
SUB	TO TRANSFER REVERSE SENSORS.		330.00	S
SUB	TO SUPPLY NUMBER PLATE.		70.00	S
SUB	TO SUPPLY SPRAY TEROSTAT		180.00	S
	SEALANT ON THE CUTTING			
SUB	TO REMOVE & REFIT CARPET & TRIMS		792.00	S
	on the rear section to give way			
	TO THE REPAIR ON THE REAR SECTION.			
SUB	TO CARRY OUT BODY CAVITY		250.00	S
	PRESERVATION.			
SUB	TO CHECK ELECTRICAL SYSTEM		250.00	S
	FOR PROPER FUNCTIONING.			
SUB	TO REPROGRAMME AFTER THE		300.00	S
	ACCIDENT REPAIR WORKS.			



TRANS**EUROKARS** Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres: 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 6476 7073 Service Fax: 6476 7417 Sales Fax: 68461700 Service Fax: 6744 9402

<sup>\*</sup>This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

<sup>&#</sup>x27;Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



## **QUOTATION**

CODE: CUSTOMER:

ADDRESS:

F0001

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY

#42-01

HONG LEONG BUILDING SINGAPORE 048581

ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 6507 3848

MODEL: JM6DJ2HAA01200187

MAZDA2 IPM HB HIGH WHITE

CHASSIS NO .: **ENGINE NO.:** 

P520484407 ET9822X

REG NO .: **REGN DATE:** 

30/11/2017

PAGE NO .:

DOCUMENT NO .:

**DOCUMENT DATE:** 

2

1504

02/10/2024

MU

PRINTED BY:

**SERVICE ADV:** 

CSP/OP CODE:

DEPT:

Lee Yao Sheng

20732

Lee Yao Sheng

WIP NO .:

POS ID:

REF. NO .:

DATE IN:

EXT. WTY:

MILEAGE:

0

### **DESCRIPTION:**

Item Description	Oty Unit Price	Gross GST amount Code	
	SGD SGD	)	
SUB SUNDRIES.	*NO STOCK 50.00	S	
DH4T-50-221 BEREAR BUMPER DJ W/SENSOR	1.00 1,024.24 STOCK 1,024.24	S	
B45A-56-146A FASTENER	7.00 2.36 *NO STOCK 16.52	. S	
D09W-50-271A STAY RR BUMPER DJ	2.00 9.78 *NO STOCK 19.56	S	
D09H-50-2J1A RETAINER LHR DJ	1.00 27.57 NO STOCK 27.57	S	
BHN1-50-0Z1A GROMMET, SCREW	4.00 2.36 *NO STOCK 9.44	S	
DFR5-50-251 BRACKET, BUMPER SKYACTIV	1.00 4.64 *NO STOCK 4.64	- S	
D09H-50-350 SHIELD LHR SPLASH M2 DJ	1.00 67.10 NO STOCK 67.10	S	
GS1D-50-EM1A TAPE, PROTECTOR	5.00 7.42 *NO STOCK 37.10	S	
D23P-67-SHO CORD, SHORT DJ	1.00 187.54 *NO STOCK 187.54	S	
KD47-67-UC5A(RETAINER REV SENSOR	4.00 15.77 *NO STOCK 63.08	S	
GMK6-67-UC1 ESENSOR, ULTRASONIC GJ/GL	2.00 184.59 <sub>STOCK</sub> 369.18	S	
KD47-67-UC1 6:SENSOR, ULTRASONIC SKYACTIV	2.00 184.59 *NO STOCK 369.18	3 \$	
DOYH-70-75Z PANEL, REAR END DJ	1.00 546.93 *NO STOCK 546.93	S S	
DOYH-71-44Y PILLAR(L), REAR OUTER	1.00 748.71 748.71	S	

		GST Code	Rate	Service/Goods	GST
					46
Parts	3,490.79	0	<b></b> '		-
Surcharge	0.00	S	9.00%	14,244.79	1,282.03
Labour	10,754.00				
Menus	0.00				
				uld there be more dama	
the process of	works you will the	n be informed fo	or your ap	proval before proceedin	g with the repairs.

	Deloie doi	001	rota
·			
Gross *	14,244.79	1,282.03	15,526.82
Less: Deposit**	0.00	0.00	0.00
Amount Due	14,244.79	1,282.03	15,526.82

Refore GST

\*\*Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE No.

Date:

Customer signature

Authorised signature

CST

Total

TRANSELROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

 Showrooms & Service Centres:
 23 Leng Kee Road Singapore 159095

 5 Ubi Close Singapore 408605
 23 Leng Kee Road Singapore 159095

 6 Sales Tel: 6395 8888 Service Tel: 6395 8899
 5 Sales Tel: 6603 6118 Service Tel: 6603 6128

 6 Sales Fax: 68461700 Service Fax: 6744 9402
 5 Sales Fax: 6476 7073 Service Fax: 6476 7417

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180,00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.