

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN		Ref:	CS/INC24060194/Avh3m4(N)		
	75 BRAS BASAH R INCOME CENTRES		Date:	26/02/2025		
	ATTN: AMANDA C	HOOI		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBK 2774E	Veh. Inspected	t	SLJ 7070G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1282477-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		24/06/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA LEXUS NX350H	c.c		2487	
	Engine No.	HIDDEN	Year of Reg.		2023	
	Chassis No.	JTJCKDEZ002011362	Colour		WHITE	
	Odometer	7982 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/60R18	BRIDGESTONE		6 mm	
	L/H Front Tyre	235/60R18	BRIDGESTONE		6 mm	
	R/H Rear Tyre	235/60R18	BRIDGESTONE		6 mm	
	L/H Rear Tyre	235/60R18	BRIDGESTONE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					1.0	
5.	General Information					
	Accident Date	19/06/2024	Inspect Date /	Time	24/06/2024 (04:53 PM)	
	Survey held at	neld at JL PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				
	•					