

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL6206D Yr Regn: 2017, March.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.D. 1496

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 133743 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11207601

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 02/10/24.

Survey held at MG Solution

Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP SMRT.

COE Expiry: _____

Estimate given during: Yes C / No C)
1st Survey

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Inve (\$ _____)

Report Format: _____

Report Format: _____

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986 Fax: 6744 4162

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

UCC. Admin

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	01-10-24
CLAIM TYPE:	T/P CLAIM
TO:	SMRT
VEHICLE DETAILS	
VEHICLE NO:	SLL6206D
MAKE & MODEL:	HONDA VEZEL
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	30 September, 2024
TIME:	1415HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT <i>new</i>	1	\$ 680.00	\$ 680.00
2	REAR FENDER RH <i>Ry</i>	1	\$ 980.00	\$ 980.00
3	REAR FENDER WHEEL ARCH <i>cut</i>	1	\$ 230.00	\$ 230.00
4	REAR BUMPER <i>new</i>	1	\$ 860.00	\$ 860.00
5	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 62.40	\$ 62.40
6	REAR QUARTER BUMPER RH <i>Deland</i>	1	\$ 280.00	\$ 280.00
7	TAILLAMP RH <i>new</i>	1	\$ 550.00	\$ 550.00

TOTAL PRICE \$ 3,642.40

LESS 20% \$ 728.48

SUB TOTAL PRICE \$ 2,913.92

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	REAR FENDER INNER ARCH CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00
3	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
TOTAL			\$	62.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,000.00	\$ 1,000.00
---	--	---	-------------	-------------

300

2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00	300
3	TUFF COAT	1	\$ 250.00	\$ 250.00	+
4	WIRING CHECK	1	\$ 100.00	\$ 100.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 250.00	\$ 250.00	+
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	+ 50
TOTAL \$ 2,700.00					

ESTIMATE REPORT

TOTAL PARTS COST	\$	2,975.92
TOTAL LABOUR COST	\$	2,700.00
TOTAL REPAIR COST	\$	5,675.92

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Admin L
H/S 02/10/24
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: