

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401447

INV Date : 19-11-2024

Reference CS/SMR24100060/Tqp3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 7447S
Insured Veh. SBS 3094K
Claim No. BUS/09/24/8007
Policy No.
Accident Date 27/09/2024
Inspection Date 02/10/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.	Ref:	CS/SMR24100060/Tqp3e2
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Date:	19/11/2024
	Code:	SMR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBS 3094K	Veh. Inspected	SMJ 7447S
Policy No.	-	Coverage	0
Claim No.	BUS/09/24/8007	Excess	\$0.00
Assign From	HUA YEN	Assign Date	02/10/2024

2. Vehicle Details

Make & Model	TOYOTA VIOS	C.C	1496
Engine No.	2NRX421529	Year of Reg.	19/03/2019
Chassis No.	MR2B23F3801168820	Colour	BRONZE
Odometer	44571 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/50 R16	YOKOHAMA	6
L/H Front Tyre	195/50 R16	YOKOHAMA	6
R/H Rear Tyre	195/50 R16	YOKOHAMA	6
L/H Rear Tyre	195/50 R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/09/2024	Inspection Date	02/10/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMJ 7447S

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$100.00	\$50.00
1	SEALANT (SN)	NECESSARY	\$300.00	\$300.00
2	TAPE, MOULDING, NO.1 (SN)	NECESSARY	\$139.80	\$139.80
4	PIECE, RR BUMPER (SN)	NECESSARY	\$23.20	\$23.20
1	COVER, RR BUMPER L/C (SN)	DEFORMED	\$818.00	\$818.00
1	SEAL, RR BUMPER SIDE (SN)	NECESSARY	\$101.00	\$101.00
1	RETAINER, RR BUMPER (SN)	CRACKED	\$236.70	\$236.70
1	REFLECTOR ASSY, REFL (SN)	CRACKED	\$129.90	\$129.90
1	PANEL SUB-ASSY, BODY (SN)	BENT	\$1,134.50	\$1,134.50
1	EXTENSION, RR FLOOR (SN)	TO REPAIR SEE LABOUR	\$194.10	\$0.00
1	TROUGH SUB-ASSY, LUG (SN)	BENT	\$161.30	\$161.30
1	PANEL SUB-ASSY, QUAR (SN)	BUCKLED	\$1,399.40	\$1,399.40
1	DUCT ASSY, QUARTER V (SN)	NOT NECESSARY	\$48.20	\$0.00
1	PANEL SUB-ASSY, LUGG (SN)	BENT	\$1,218.30	\$1,218.30
1	WEATHERSTRIP, LUGGAG (SN)	NOT NECESSARY	\$242.90	\$0.00
2	ARM SUB-ASSY, LUG CO (SN)	NOT NECESSARY	\$182.00	\$0.00
1	TAPE, BLACK OUT, NO. (SN)	NECESSARY	\$66.50	\$66.50
1	CHECK ASSY, FR DOOR (SN)	NOT NECESSARY	\$255.50	\$0.00
1	PANEL SUB-ASSY, FR D (SN)	BENT	\$1,688.50	\$1,688.50
1	HANDLE ASSY, FR DOOR (SN)	NOT NECESSARY	\$612.80	\$0.00
1	COVER, FR DOOR OUTSI (SN)	CUT	\$47.00	\$47.00
1	COVER, FR DOOR OUTSI (SN)	CUT	\$84.10	\$84.10
1	LOCK ASSY, FR DOOR W (SN)	NOT NECESSARY	\$840.30	\$0.00
1	HINGE ASSY, FR DOOR (SN)	NOT NECESSARY	\$135.40	\$0.00
1	HINGE ASSY, FR DOOR (SN)	NOT NECESSARY	\$153.00	\$0.00
1	PANEL SUB-ASSY, RR D (SN)	BENT	\$1,448.40	\$1,448.40
1	TAPE, BLACK OUT, NO. (SN)	NECESSARY	\$60.40	\$60.40
1	WEATHERSTRIP, RR DO (SN)	NOT NECESSARY	\$248.40	\$0.00
1	CHECK ASSY, RR DOOR (SN)	NOT NECESSARY	\$255.50	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	HANDLE ASSY, DOOR, O (SN)	CUT	\$204.10	\$204.10
1	COVER, RR DOOR OUTSI (SN)	CUT	\$84.10	\$84.10
1	FRAME SUB-ASSY, RR D (SN)	NOT NECESSARY	\$268.20	\$0.00
1	LOCK ASSY, RR DOOR W (SN)	NOT NECESSARY	\$779.30	\$0.00
1	HINGE ASSY, RR DOOR (SN)	NOT NECESSARY	\$135.40	\$0.00
1	HINGE ASSY, RR DOOR (SN)	NOT NECESSARY	\$135.40	\$0.00
1	REGULATOR SUB-ASSY	NOT NECESSARY	\$262.10	\$0.00
1	EMBLEM, LUGGAGE COMP (SN)	NECESSARY	\$85.60	\$85.60
1	EMBLEM, SYMBOL (SN)	NECESSARY	\$66.30	\$66.30
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	\$63.20	\$63.20
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	\$49.20	\$49.20
1	LAMP ASSY, RR COMBIN (SN)	CRACKED	\$976.00	\$976.00
1	LAMP ASSY, RR, RH (SN)	CRACKED	\$637.00	\$637.00
1	RETAINER, RR BUMPER (SN)	DEFORMED	\$91.40	\$91.40
1	WHEEL, DISC (SN)	CUT	\$2,687.30	\$2,687.30
2	SIKA 182010 SIKA TACK GO! (BLA (SN)	NECESSARY	\$216.00	\$216.00
1	SIKA 207. G+P ADHESIVE PRIMER (SN)	NECESSARY	\$200.00	\$200.00
1	PANEL BONDING AD (SN)	NECESSARY	\$267.20	\$267.20
			\$19,532.90	\$14,734.40

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND CONDUCT LEAK TEST		\$198.00	\$198.00
	TRANSFER RH FRT AND REAR DOOR MECHANISM		\$792.00	\$792.00
	R/I REAR WINDSCREEN		\$792.00	\$792.00
	R/I INTERIOR UPHOLSTERY		\$792.00	\$792.00
	DRILL HOLE AND INSTALL REVERSE SENSOR		\$198.00	\$198.00
	TO RESET ECU AND REPROGRAMME		\$198.00	\$198.00
	CONDUCT WHEEL ALIGNMENT		\$198.00	\$198.00
	TRANSFER TYRE TO NEW RIM		\$198.00	\$198.00
	TRANSFER BOOTLID MECHANISM AND REVERSE CAMERA		\$396.00	\$396.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPL ACC AFF PARTS AND PANEL. INCLUSIVE OF THE REPAIR OF EXTENSION, RR FLOOR		\$6,336.00	\$3,960.00
	RESPRAY ACC AFF AREA		\$5,248.00	\$3,280.00
			\$15,346.00	\$11,002.00
GRAND TOTAL			\$34,878.90	\$25,736.40
	RECOMMENDED COST OF REPAIRS			\$25,736.40
Report Ref No: CS/SMR24100060/Tqp3e2				

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	30/09/2024 17:01 (SGT)
Reported by	Actual Driver
Date of Accident	27/09/2024 12:26 (SGT)
Exact Location of Accident	Jurong West, Singapore
Additional Location Information	JURONG WEST ST 63, LAMP POST 16
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ7447S
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN KIM LEE
NRIC No	SXXXX845B
Email Address	-
Mobile Phone No	-
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7230004347

DRIVER

Name of Driver	THOMAS TAN KEAT HAO
NRIC No	TXXXX597A
Date Of Birth	
Occupation	Indoor
Driving Pass Date	22/02/2022
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	2 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	
Alt. Phone Number	-
Email Address	-
Address	
Address complement	
Postcode	207227
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBS3094K
Vehicle Manufacturer	Volvo

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	ROSLEY BIN ABDUL SAMAD
NRIC No	SXXXX495B
Contact Number	(Phone) +65-98238872
Address	BLK 408 JURONG WEST STREET 42
Address complement	#06-667
Postcode	640408
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

WITNESS DETAILS

WITNESS 1

Name	LOUIS LIU
Phone	(Phone) +65-96193218
Email	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

On the 27 Sep 2024, around 1226 hours, I was turning right from Jurong West St 61 into Jurong West St 63 when I saw a Malay lady lying on the road beside the ~~ped~~ pedestrian crossing at lamp post 16. She was holding her head with her hands, and her bicycle had fallen beside her. The lady was involved with another accident with car SIVQ3360K (Driver: Alex, Hp: +65 9668 5654). I did not witness this accident occurring.

I immediately filter left from Lane 1 to Lane 2 and stopped my car slightly in front of the fallen Malay lady. Hazard lights were turned on. I rendered assistance to the lady and called for an ambulance. Another passer-by, A1, ~~came~~ come shortly after, and moved the lady with me to the pedestrian crossing upon advice of the SCDF dispatcher to ensure her safety.

Whilst tending to the lady and waiting for arrival of ambulance, a SBS Transit bus (license plate SBS 3094 K) made a right turn from Jurong West st 61 into Jurong West St 63 and hit the right rear bumper and passenger door area of my stationary car. I did not see the accident happening, only that there was a loud bang. I turned around and saw the left corner of the bus stuck into my car.

B1, the driver of the bus, said that as he was making the right turn, he was watching out for pedestrians crossing the road on his bus's right blind spot. He says his vision was obstructed by the pillars of the MRT tracks and surrounding foliage, and did not see my car until it's too late, resulting in the left corner of his bus clipping my car.

Details of witness A1:

Louis Liu
+65 9619 3218

Details of B1:

Rosley Bin Abdul Samad
NRIC: S1596495B
HP: +65 9823 8872
DOB: 16-12-1963
ADDR: APT BLK 408 JURONG WEST STREET 42
S (640408)

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)


PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S




PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S






PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S






PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S




PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S




PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S




PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S






PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S




PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S





PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S





PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S




PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S



PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 20 of 20)

PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMJ 7447S

