

Rajes (LKK Auto)

From: Susan Low <liusbro@gmail.com>
Sent: Wednesday, October 2, 2024 3:18 PM
To: Claims Dept of CTI
Subject: Our Ref: GBF272B240817 Your Ref: SLR1753S
Attachments: GBF272B Search.pdf; GBF272B240917.pdf

CAUTION: This email originated from outside the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Vehicle to be surveyed:	GBF272B
3rd Party Insured Vehicle:	SLR1753S
Date of Accident:	17/09/2024
Location of Accident:	Republic Plaza 1 Drop Off
Name of Workshop:	Liu's Brother Auto Engineering Workshop
Address of Survey Location:	No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop as soon as possible.

Kindly arrange

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730

Date of Survey:	
Name of Authorise Surveyor:	