



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100075/Knp3m4
(BUDGET DIRECT INSURANCE)	Date:	01/11/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 3898E	Veh. Inspected	SNK 2993Y
Policy No.	P10265145R04	Coverage	0
Claim No.	C10031412/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	03/10/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE 1.5G A	C.C	1496
Engine No.	L15B5004158	Year of Reg.	13/06/2017
Chassis No.	GK81103534	Colour	METALLIC GREY
Odometer	169505 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	CONTINENTAL	7
L/H Front Tyre	185/60R15	CONTINENTAL	7
R/H Rear Tyre	185/60R15	MICHELIN	8
L/H Rear Tyre	185/60R15	MICHELIN	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2024	Inspection Date	04/10/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days