

AES. REC. BY: Tauyph

REF:

TMI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

ML LokeVeh No: SHA8824L Yr Regn: 2019, 05Type: M.Car / M.Cycle / Bus / Van / Lorry / Trax / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 778867 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDRB3E4603081311Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195/65R1527

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 3/60/24Survey held at Comfort Layan

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.R. / C.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/10/2024
Vehicle Reg. No.:	SHA8824L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 (A)	Vehicle Reg. Date:	31/05/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	2ZR2C28206	Chassis No:	JTDKB3FU603081311
Odometer:	778864 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	4,325.16
Labour	12.00
Paintwork Labour	2,380.00
Towing	0.00
	0.00
Gross Total (\$\$)	6,717.16
+ GST 9.00% (\$\$)	604.54
Nett Amount (\$\$)	7,321.70

This claim is handled by: LOKE WEI YIENG

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 02 Oct 2024)

Parts: 144 **TOYOTA PRIUS 1.5 (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA8824L/02/10/2024 16:07

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER SUB ASSY RH	25.00	0.00	st *1,111.93 FL
2	1		*FRONT FENDER HYBRID EMBLEM RH	25.00	0.00	rel *86.50 FL
3	1		*FRONT FENDER SHIELD RH	25.00	0.00	de *198.50 FL
4	1		*FRONT BUMPER COVER	25.00	0.00	Ry *586.18 FL
5	1		*FRONT BUMPER CLIPS	25.00	0.00	x *22.00 FL
6	1		*FRT DOOR PANEL RH	25.00	0.00	Ry *1,264.00 FL
7	1		*ROCKER PANEL GARNISH RH	25.00	0.00	Ry *576.00 FL
8	1		*FRT WHEEL RIM RH	25.00	0.00	Ad *1,555.10 FL
9	1		*FRT DOOR COMFORT LOGO RH	0.00	0.00	int *75.00 F
10	1		*RENEW ADVERTISEMENT	0.00	0.00	rel *200.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	5,675.21
- List Item Discount on L Items (S\$)	1,350.05
Total Parts (S\$)	4,325.16

ComfortDelGro Engineering Pte Ltd/SHA8824L/02/10/2024 16:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)			12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	760 1,000.00
2	SPRAY PAINTING CHARGE	New	840 1,200.00
3	TRANSFER OF DOOR	New	X 120.00
4	TUFF KOTE	New	30 60.00
Gross Labour Cost (S\$)			2,380.00

ComfortDelGro Engineering Pte Ltd/SHA8824L/02/10/2024 16:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
'WP' 3/10/24 e
1/5 Resurvey after repair
Tanpin 01/10/2024 an
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: