



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060197/Unh3
16 RAFFLES QUAY	Date:	24/06/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3047E	Veh. Inspected	SLB 7833P
Policy No.	-	Coverage	0
Claim No.	D24005497MFCT	Excess	\$0.00
Assign From	JOANNE TAN	Assign Date	24/06/2024

2. Vehicle Details

Make & Model	TOYOTA WISH (A)	C.C	1798
Engine No.	2ZR1753263	Year of Reg.	22/04/2016
Chassis No.	JTDGG20W10J003980	Colour	RED
Odometer	108335 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	YOKOHAMA	6
L/H Front Tyre	195/65R15	YOKOHAMA	6
R/H Rear Tyre	195/65R15	YOKOHAMA	6
L/H Rear Tyre	195/65R15	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/06/2024	Inspection Date	24/06/2024
Survey held at	9002 TAMPINES ST 93 #01-72 (S) 528836-WHEELZ 4 YOU		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days